AFWAL-TR-80-3023

AD A 096759


ADVANCED FIBER REINFORCED THERMOPLASTIC STRUCTURES

April 1980

Technical Report AFWAL-TR-80-3023 Final Report for Period August 1975 - August 1979

Approved For Public Release, Distribution Unlimited

Flight Dynamics Laboratory Air Force Wright Aeronautical Laboratories Air Force Systems Command Wright-Patterson Air Force Base, Ohio 45424



Boeing Aerospace Company Military Airplane Development P.O. Box 3999 Seattle, Washington 98124

THIS BOCUMENT IS BESS ? THE COPY FURNISHED TO DOG 3 WARRE SIGNIFICANT NUMBER OF PAGES WHICH DO POS Exproduce Legibly.

410058 81 3 24 056

NOTICE

When Government drawings, specifications, or any other data used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

This report has been reviewed by the Office of Public Affairs (ASD/PA) and is releaseable to the National Technical Information Service (NTIS). At NTIS, it will be available to the general public, including foreign nations.

This technical report has been reviewed and is approved for publication.

George T. Estill

Project Engineer

Structural Concepts Evaluation Gp

Floyd G. Hemmig, Captain / USAF Actq Chf. Structural Concepts Br

Structures & Dynamics Division

FOR THE COMMANDER

RALPH L. KUSTER, Jr., Colonel, USAF Chief, Structures & Dynamics Division

"If your address has changed, if you wish to be removed from our mailing list, or if the addressee is no longer employed by your organization please notify AFWAL/FIBCB, W-PAFB, OH 45433 to help us maintain a current mailing Tist".

Copies of this report should not be returned unless return is required by security considerations, contractual obligations, or notice on a specific

AIR FORCE/56780/14 January 1981 — 250

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

	SECURITY CLASSIFICATION OF THIS PAGE (V"nen Data Entered)			
:	REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM		
00	L. REPORT NUMBER 2. GOVT ACCESSION NO.	3 DECIPIENT'S CATALOG NUMBER		
	AFWALHTR-80-3023] HD-H076	2/9/		
	A. TITLE (and Subtitle)	S. TYPE OF REBOAT & PERIOD COVERED	_	
(6)	ADVANCED FIBER REINFORCED THERMOPLASTIC STRUCTURES			
4	Company of the Control of the Contro	6 PERFORMING ONO. REPORT NUMBER		
\ .		8 CONTRACT OR GRANT NUMBER(3)		
110	J. T./Hoggatt /			
(1	S./Oken	F33615-76-C-3048		
- A	9. PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK		
	Boeing Aerospace Company	Program Etament 82201F		
	Box 3707 (76)	<u>Project 2401</u>) Task 240103 Work Unit 24010318		
	Seattle, WA 98124	12 REPORT DATE		
	11. CONTROLLING OFFICE NAME AND ADDRESS	Apr 1980 (17) 03		
	Air Force Wright Aeronautical Laboratories (AFSC)	13. NUMBER OF PAGES		
	Wright-Patterson AFB, OH 45433 14 MONITORING AGENCY NAME & ADDRESS(11 different from Confine Diffice)	15 SECURITY CLASS (of this report)		
	(12)			
		Unclassified		
	7334	15a. DECLASSIFICATION DOWNSRADING SCHEDULE		
	16. DISTRIBUTION STATEMENT (of this Report)			
	Approved for public release; distribution unlimited	4		
	Approved for public release, discrimination diffinites			
	17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different fro	om Kepori)		
	18 SUPPLEMENTARY NOTES			
]		
	19 KEY WORDS (Continue on reverse side if necessary and identify by block number)		
•	Composites, Thermoplastic, Polysulfone, Graphite,	Elevator		
	, , , , , , , , , , , , , , , , , , , ,			
	,			
•	20 ABSTRACT (Continue on reverse side if necessary and identity by block number)			
	I The objective of the program was to demonstrate th	e performance and cost savings		
	of graphite/polysulfone. This objective was attai program which cultimated in the design, fabricatio	ned inrough a infrieen task n and test of a full scale		
	elevator torque box. The P-1700 polysulfone resin	was selected and used with		
	A-S unidirectional graphite fibers (Hercules 3004/	A-S/P1700 prepreg) and with		
	T-300 woven graphite fibers (Hexcel T-3004/23x24, concepts, consolidation and post forming processes	811 Satin Prepreg). Tooling		
	were developed. The graphite/thermoplastic elevat	or had a 27% weight (OVER)		
	<u> </u>			
	DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE	UNCLASSIFIED		

410058

SECURITY CLASSIFICATION OF THIS PAGE (Wien Data Entered)

THE PROPERTY OF THE PROPERTY O

SECURITY CLASSIFICATION OF THIS PAGE(When Date Entered) 'savings as compared to the aluminum elevator, and a cost saving of 20%, by the tenth elevator shipset. A limited study of a Union Carbide proprietary thermoplastic, known as PKXA, which has much improved solvent resistance as compared to P-1700 polysulfone, was conducted. This limited study showed that PKXA appeared to be a viable substitute for P-1700 polysulfone. It is recommended that a further study of PKXA be made in order to further optimize the manufacturing procedures for it.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE(When Date Entered)

Foreword

This report summarizes the work performed by the Boeing Aerospace Company (BAC) under the Air Force Contract F33615-76-C-3048 during the period of August 1, 1976 through August 1, 1979.

This program was sponsored by the Material's Laboratory and the Flight Dynamics Directorate, Air Force Wright Aeronautical Laboratories (AFSC), Wright-Patterson AF Base, Ohio. The program monitors were G. Estill, AFFDL, Capt. F. T. Bannink, AFFDL and H. S. Reinert, AFML.

This contract was performed and managed by Engineering Technology personnel at BAC. Mr. J. T. Hoggatt and D. B. Arnold were the program managers and Mr. S. Oken the technical leader. The principal contributors during the course of the program were K. Hernley, design; A. L. Dobyns, stress; E. E. House and S. G. Hill, materials and processes; D. L. Muretta and D. A. Anderson, manufacturing research; and J. D. Swenson, testing.

Accession For
MIS THAT
7
_ Applicability Tages
Avail 2nd/or Dist . Special
1 55
A
7

TABLE OF CONTENTS

		PAGE
SECTION 1.1 1.2	1.0 INTRODUCTION SUMMARY	1 1 1
Section	2.0 RESIN AND FIBER SELECTION/EVALUATION	5
3.1	3.0 CONCEPTUAL DESIGN/CONCEPT EVALUATION INTRODUCTION 3.1.1 COST PROCEDURE	11 11 11
3.3 3.4	YC-14 FUSELAGE BODY SECTION 43 LARGE TRANSPORT A/C FUSELAGE PANEL FIREBEE DRONE SECTION COMPONENTS YC-14 STIFFENED LAMINATE WING BOX	17 17 24 24
3.6 3.7 3.8	YC-14 HONEYCOMB WING BOX YC-14 HORIZOHTAL STABILIZER COMPASS COPE HORIZOHTAL STABILIZER CONCLUSIONS	34 34 38 45
	4.0 MANUFACTURING DEVELOPMENT CONSOLIDATION	47 47
7.1	4.1.1 PRESS CONSOLIDATION 4.1.2 AUTOCLAVE COMSOLIDATION 4.1.3 PULTRUSION COMPACTION 4.1.4 ROLL FORMING COMPACTION	47 50 50
4.2	POST FORMING 4.2.1 PRESS MATCH DIE POST FORMING 4.2.2 AUTOCLAVE POST FORMING 4.2.3 VACUUM FORMING	52 52 54 54
4.3	4.2.3 VACUUM FORMING BOMDING/JOINING METHODS 4.3.1 FUSION BONDING 4.3.2 ADHESIVE BONDING	57 57 57 66
4.4	4.3.3 MECHNICAL FASTENING CHOPPED FIBER MOLDING 4.4.1 INJECTION MOLDING 4.4.2 CLOSE DIE MOLDING	66 70 70 70
SECTION	5.0 FIELD MAINTENANCE/REPAIR METHODS	89
	6.0 SUBCOMPONENT EVALUATION IN-PLANE SHEAR TESTS JOINT TESTS 6.2.1 30MDED JOINTS	99 99 103
6.4	6.2.1 SOMBED JOINTS 6.2.2 MECHANICAL ATTACHMENT JOINTS SHEAR PAMEL BUCKLING TESTS COMPRESSION PAMEL BUCKLING TESTS FRACTURE PAMEL TESTS	106 114 119 134 145
	LOAD INTRODUCTION TESTS	147

TABLE OF CONTENTS (Cont'd.)

	PAGE
SECTION 7.0 YC-14 ELEVATOR FULL-SCALE DESIGN AND FABRICATION	161
7.1 DESIGN REQUIREMENTS AND CRITERIA 7.2 PRELIMINARY DESIGN 7.2.1 "Z" STIFFENED PANEL CONCEPT 7.2.2 CORRUGATED STIFFENED PANEL CONCEPTS 7.2.3 HONEYCOMB STIFFENED COVER PANEL CONCEPT 7.2.4 PRELIMINARY DESIGN STUDY RESULTS 7.3 DETAIL DESIGN AND ANALYSIS 7.3.1 DESIGN 7.3.2 ANALYSIS	161 169 169 173 173 178 182 183 183
SECTION 8.0 FULL-SCALE ELEVATOR TOOLING AND FABRICATION	201
8.1 ELEVATOR DETAIL FABRICATION 8.2 SUBASSEMBLY FABRICATION 8.3 ELEVATOR ASSEMBLY TOOLING AND FABRICATION	201 201 206
SECTION 9.0 DEMONSTRATION ARTICLE TESTING	219
SECTION 10.0 COST AND PAYOFF ANALYSIS	247
SECTION 11.0 PKXA EVALUATION	253

LIST OF ILLUSTRATIONS

Figure	<u>Title</u>	<u>Page</u>
1	Effect of Temperature on Flexure Strength -	6
	Graphite/Polysulfone Composites	
2	Effect of Temperature on Flexure Modulus	7
3	Effect of Temperature on Interlaminar Shear	7
4	Effect of Temperature on Tensile Strength	8
5	Effect of Temperature on Tensile Modulus	8
6	Part Fabrication Time	14
7	Assembly Time	15
8	Tooling Time	16
9	YC-14 Fuselage Structure Centerline Diagram	18
10	Fuselage Section 43 - Details	19
11	Typical Graphite Reinforced Polysulfone	21
	Body Structure (Unpressurized)	
12	Firebee Drone Profile and Selected Gr/Ps Components	25
13	Prototype Gr/Ps Component Design Concept Details	26
14	Skin Installation - Centerbody Section	27

<u>Title</u>	Page
Delivered GRTP Components for the Firebee	29
Drone Center Body Section	
YC-14 Wing Structure Diagram	31
YC-14 Stiffened Laminate Wing Concept	32
Stiffened Laminate Stringer Configurations	33
YC-14 Honeycomb Wing Concept	35
YC-14 Horizontal Stabilizer Centerline Diagram	39
Typical Spar/Rib Attachment	40
Compass Cope Materials Systems	42
Compass Cope - Horizontal Stabilizer Composite	43
Design	
Compass Cope Horizontal Stabilizer Details	44
Press Consolidated Unidirectional Laminate	49
Press Consolidated 181 Style Graphite Fabric	49
Laminate	
Thermoplastic Pultrusion Facility	51
Graphite Thermoplastic Pultruded Sections	53
Press Match-Die Moided Post Formed Channel	55
Press Holded Shapes - Silicone Plug Hold	55
	Delivered GRTP Components for the Firebee Drone Center Body Section YC-14 Wing Structure Diagram YC-14 Stiffened Laminate Wing Concept Stiffened Laminate Stringer Configurations YC-14 Honeycomb Wing Concept YC-14 Horizontal Stabilizer Centerline Diagram Typical Spar/Rib Attachment Compass Cope Materials Systems Compass Cope - Horizontal Stabilizer Composite Design Compass Cope Horizontal Stabilizer Details Press Consolidated Unidirectional Laminate Press Consolidated Unidirectional Laminate Thermoplastic Pultrusion Facility Graphite Thermoplastic Pultruded Sections Press Match-Die Molded Post Formed Channel

Figure	<u>Title</u>	Page
31	Shear Web Molded From (0°,90°) _S Graphite	56
	Tape Composite	
32	Shear Web Molded From Graphite Fabric	56
33	Vacuum Formed Shear Web (0°,90°) _S Sheet Stock	58
34	Vacuum Formed Shear Heb Graphite Fabric	58
35	Chemithon Thermoforming Machine	59
36	Vacuum Forming Chamber-Schematic	60
37	Graphite Thermoplastic Vacuum Forming -	61
	Part Removal	
38	Polysulfone Adhesive Films with Self Contained	63
	Heating Wires and Screen	
39	Fusion Joint - Resistant Heating Wires	63
40	Fusion Joint - Close Up	64
41	Fusion Joint - Resistant Heating Screen	64
42	Electromagnetic Bonding	65
43	Punched Hole - 1/4 Diameter (50%)	68
44	Drilled/Reamed Hole - 1/4 Diameter (50X)	69

<u>Figure</u>	<u>Title</u>	Page
45	YC-14 Elevator Molded Link Fitting	73
46	Molded Fitting - Preformed Fabric Pan	75
47	Molded Fitting - Pan Compaction Tool and Caul Plates	75
48	Molded Fitting - Compacted Pan Prior to Trim	76
49	Molded Fitting - Chopped Graphite Fiber Molded Truss	78
50	Molded Fitting - Truss Compaction Tool	79
51	Molded Fittings - Fabric Truss	79
52	Molded Fitting - Detail Parts and Fusion Assembly Tool	80
53	Molded Fitting - Fusion Tool with Details Installed	80
54	Molded Fitting - Details and Pans in Tool	81
55	Molded Fittings - Fusion Assembly Tool Ready for Press	81
56	Molded Fitting - Graphite/Polysulfone	82

<u>Figure</u>	<u>Title</u>	<u>Page</u>
57	Molded Fitting - Test Set-Up Without Side Plate	83
58	Molded Fitting - Test Set-Up	83
59	Molded Fitting - Test Load Conditions	84
60	Molded Fitting - Pull-Out Test	86
61	Fabric Truss Molded Fitting Failure	87
62	Chopped Fiber Truss Molded Fitting Failure	87
63	Fusion Bond Damage Repair	90
64	Fusion Bond Repair - Vacuum Bag and Heat Source	91
65	Fusion Bond Repair Cross Section	92
66	Adhesive Bond Repair	94
67	Repair Panel-Failed Specimens	. 96
68	In-Plane Shear	101
69	Rail Shear Static Test Set-Up	102
70	Failed Rail Shear Specimens	103
71	Failed Rail Shear Specimens - Doublers Bonded in Attachment Areas	104
72	Failed Rail Shear Specimen-Rails Bonded In-Place	105

<u>Figure</u>	<u>Title</u>	Page
73	Rail Shear Fatigue Data	107
74	Rail Shear Failed Specimens	108
75	Lap Shear Specimen	109
76	Fusion Bonded Joint	112
77	Fusion Bond Lap Shear Fatigue (Fabric at <u>+4</u> 5)	115
78	Fusion Bond - Rail Shear Specimen	116
79	Mechanical Attachment Joint Test Data	117
80	Failed Mechanical Attachment Specimens	118
81	Mechanical Attachment Fatigue Specimen Failures	121
82	Shear Beam Element	122
83	Chord Details - Beam Element	124
84	Beam Element Details	125
85	Beam Element Assembly	126
86	Beam Element - Test Setup	127
87	Shear Beam Overall Test Set-Up	128

である。 では、1000年のでは、1

<u>Figure</u>	<u>Title</u>	Page
102	Compression Panel Lateral Displacement Profile-	145
	Zero and 100% Ultimate Load	
103	Compression Fanel Fatigue	147
104	Slotted Panel Test Specimen	148
105	Fracture Panel Failure and Control Panels	150
106	<u>+45</u> Graphite/Epoxy Center Notched Panel Fracture	151
	Response	
107	Load Introduction Test Element	153
108	Static Test No. 1 Setup	155
109	Static Test No. 2 and Fatigue Test Setup	156
110	Load Introduction Box - Test Setup	157
111	Load Introduction Box - Test Set-Up, Front View	158
112	Load Introduction Box - Test Set-Up. Side Yiew	158
113	Static Test No. 3, Side Load Test Setup	159
114	YC-14 Outboard Elevator GJ Comparisons	165

Figure	<u>Title</u>	Page
88	Shear Panel Instrumentation	129
89	Shear Beam Test Schematic - Moire' Displacement	130
90	Shear Panel Moire' Fringe Zero Load	131
91	Shear Panel Moire' Fringe 50% Ultimate Load	132
92	Shear Panel Moire' Fringe 100% Ultimate Load	133
93	Shear Panel Schematic - Latera' Displacement Line	135
94	"T" Stiffener Panel Displacement Profile Zero and 100% Shear Load	136
95	Shear Buckling - Theory vs Test	137
96	Shear Buckling Fatigue Test	138
97	Compression Buckling - Panel Element	140
98	Compression Panel Instrumentation	141
99	Compression Panel Test Set-Up	142
100	Compression Panel Test - Back Side	143
10ì	Compression Panel Moire' Fringe - 100% Ultimate	144

<u>Figure</u>	<u>Title</u>	<u>Page</u>
115	YC-14 Outboard Elevator El Comparisons	166
116	Fatigue of Intermediate Strength Graphite/Epoxy	168
117	YC-14 Elevator Schematic	170
118	YC-14 Elevator Gr/Ps Z Stiffened Cover Concept	171
119	YC-14 Elevator Graphite/Polysulfone Corrugated ''iffened Cover Concept	175
120	Graphite/Epoxy Elevator Test Component	177
121	Honeycomb Stiffened Design Concept	179
122	Elevator Splice Locations	184
123	YC-14 Elevator Fairings	185
124	GRTP Outboard Elevator YC-14 (Sh 1)	187
125	GRTP Outboard Elevator YC-14 (Sh 2)	189
126	GRTP Outboard Elevator YC-14 (Sh 3)	191
127	GRTP Outboard Elevator YC-14 (Sh 4)	193
128	GRTP Outboard Elevator YC-14 (Sh 5)	195
129	GRTP Outboard Elevator YC-14 (Sh 6)	197

<u>Figure</u>	<u>Title</u>	Page
130	Differential Thermal Growth	199
131	YC-14 GR/PS Elevator SAMECS Plot	200
132	Thermoplastic Elevator Assembly Sequence	202
133	Stiffener Match Die Tooling and Details	203
134	Matched Die Rib Tooling and Completed Rib	204
135	YC-14 Elevator Subassemblies	205
136	YC-14 Elevator Spar Web Assemblies	205
137	Details Located in Fusion Assembly Tool	207
138	Details in Fusion Tool with Chord Pressure Bars in Place	208
139	Fusion Tool, Loaded, Bagged and Ready for Fusion	209
140	Completed Side Panel Fusion Assembly-30 Inch Length	210
141	YC-14 Elevator Large Section Assembly Fixture -	211

THE THE THE PARTY OF THE PARTY

<u>Figure</u>	<u>Title</u>				
342	YC-14 Elevator Large Section Assembly Fixture - Side View	211			
143	YC-14 Elevator Middle and Small Section Assembly Fixture	212			
144	Details Placed in Assembly Fixture	212			
145	YC-14 Elevator Spar Web and Chord Installation	213			
146	YC-14 Elevator Section Assembly	213			
147a	Elevator Assembly - No Covers	215			
147b	YC-14 Elevator No. 2				
148	YC-14 Elevator - Typical Visu-Lok Blind Fastener Installation	217			
149	Strain Gage Locations	220			
150	Strain Gage Locations	221			
151	Loading Points and Deflection Indicator Locations	222			
152	Elevator Test Set-Up	223			
153	GR/TP YC-14 Elevator Box Test - Test Article and Fixtures				
154	GR/TP YC-14 Elevator Box Test - Test Article and Fixtures	225			

Figure	<u>Title</u>	Page
155	GR/TP Elevator Box Test - Test Article and Fixtures	226
156	GR/TP YC-14 Elevator Box Test - Instrumentation and Control	227
157	Test - Loading Schedule, Graphite Thermoplastic YC-14 Elevator Box Test	228
158	Test - Loading Schedule, Graphite Thermoplastic YC-14 Elevator Box Test	229
159	Test - Loading Schedule, Graphite Thermoplastic YC-14 Elevator Box Test	230
160	Test - Loading Schedule, Graphite Thermoplastic YC-14 Elevator Box Test	231
161	Test - Loading Schedule, Graphite Thermoplastic YC-14 Elevator Box Test	232
162	Upper Cover Failure - Test 1.9 - Elevator Box #1	234
163	Front Spar Failure - Test 1.9 - Elevator Box #1	235
164	Front Spar Failure - Test 1.9 - Elevator Box #1	236
165	Front Spar Failure - Test 2.3 - Elevator Box #2	237
166	Front Spar Failure - Test 2.3 - Elevator Box #2	238
167	Front Spar Repair - Elevator Box #2	239

<u>Figure</u>	<u>Title</u>	Page
168	Lower Cover/Rear Spar Bond Failure - Test 2.4	240
	Elevator Box #2	
169	Lower Cover Failure - Test 2.4 - Elevator Box #2	241
170	Load Point and EDI Locations GR/PKXA YC-14	243
	Elevator Box #3	
171	GR/PKXA YC-14 Elevator Box #3 - Test Article in	244
	Fixtures	
172	GR/PKXA YC-14 Elevator Box #3 - Test Article in	245
	Fixtures	
173	Chemical Formulas of PKXA and P-1700 Polysulfone	254
174	PKXA-P-1700 Rail Shear Fatigue Data Comparison	258

LIST OF TABLES

<u>Table</u>	<u>Title</u>	Page
1	Thermoplastic Prepregs	6
2	Graphite Fabric/P1700 Average Test Data	9
3	P1700/A-S Tape Laminate Properties	9
4	Properties of Polyphenylene Sulfide Graphite	10
	Fiber Reinforced Molding Compound	
5	Conceptual Design and Evaluation Components	12
6	Cost Factors and Assumptions	12
7	Fabrication Costs for Advanced Composite Designs	20
	YC-14 Fuselage Body Section 43	
8	Fabrication Cost for Advanced Composite Designs	23
	Large Transport A/C Fuselage Panel	
9	Fabrication Costs for Advanced Composite Designs	30
	Firebee Drone Body Component	
10	Wing Box Weight Summary-Stiffened Laminate Design	35
11	Fabrication Costs for Advanced Composite Designs	35
	YC-14 Stiffened Laminate Wing Box	
12	Wing Box Weight Summary - Honeycomb Concept	37
13	Fabrication Costs for Advanced Composite Design -	37
	VC-14 Honeycomb Wing Roy	

LIST OF TABLES

<u>Table</u>	<u>Title</u>	Page
14	YC-14 Advanced Composite Horizontal Stabilizer	41
	Cost Estimate	
15	Compass Cope Advanced Composite Horizontal	46
	Stabilizer Cost Estimate	
16	Compass Cope Horizontal Stabilizer Cost Estimate -	46
	Glass/Epoxy and Graphite/Polysulfone	
17	Task IV - Manufacturing Development	48
18	Processing Time for Consolidation	48
10	•	67
19	Adhesive Lap Shear Strengths	67
20	Bonding Methods - Typical Values	67
21	Attachment Studies - Hole Fabrication Evaluation	68
22	Attachment Studies - Reamed Hole Evaluation	69
23	Injection Molding Material Flexural Properties -	71
	Ryton PPS (Phillips)	,,
24	Repair Panel Static Tests	95
24	Reputt Fullet Statete fests	J J
25	Repair Panel Fatigue Tests	95
26	Subcomponent Tests	100

LIST OF TABLES

<u>Table</u>	<u> </u>	Page
27	Rail Shear Static Tests - <u>+</u> 45 Graphite Fabric/ P1700	100
28	Adhesive Lap Shear Strengths	111
29	Lap Shear Strength (psi) (4 plies <u>+</u> 45 Fabric)	113
30	Mechanical Attachment Fatigue Data	120
31	Fracture Panel Tests	149
32	Cost Summary - Graphite Polysulfone YC-14 Elevator	181
33	Areas of Cost Savings	248
34	Processing Time for Post Forming	250
35	Element Cost Savings with GR/TP	250
36	PKXA Static Rail Shear Test Results	254
37	PKXA Mechanical Attachment, Lap Shear Test Results	256
38	PKXA Fusion Bond, Lap Shear Test Results	256
39	PKXA Fracture Panel, Tension Test Results	257
40	PKXA Rail Shear Fatigue Results	257
41	PKXA Polysulfone Static Element Test Data Comparison	258

SECTION 1.0

1.1 INTRODUCTION

This program was performed to demonstrate the improved performance and cost savings made available by the use of Advanced Fiber Reinforced Thermoplastics (AFRTP) in aircraft structures. To demonstrate these improvements, full size aircraft components were fabricated and tested. The YC-14 left-hand outboard elevator was selected as the component to be used in this evaluation. This part has a span of 19 ft and a maximum chord of 18 in. The studies showed that a graphite/thermoplastic elevator offers a 27 percent weight savings and 20 percent cost savings over the presently used aluminum elevator by the tenth elevator shipset. In this program we:

- o Evaluated and refined manufacturing techniques for use with AFRTP's.
- o Demonstrated the potential of AFRTP's to reduce the fabrication and assembly costs of aircraft structures.
- o Demonstrated the structural integrity and durability of AFRTP components.
- o Developed repai. procedures and logistics for maintaining composite structures.
- o Laid the groundwork for the production and flight service test of an AFRTP component.

1.2 SUMMARY

To attain the objectives of this program the 13 tasks described below were performed.

Task I--Resin and Fiber Selection/Evaluation

P-1700 polysulfone was selected as the thermoplastic matrix material to be used in this program. Graphite fibers in both tape and fabric form were tested to obtain mechanical and environmental properties. Molding components incorporating short graphite fibers were investigated for use as hinge fitting material.

Task II -- Conceptual Design/Concept Evaluation

Seven major aircraft and missile components were selected for GRTP application studies. Cost and weight savings were identified for each of the designs and compared to equivalent graphite/epoxy and aluminum designs.

Task III--Preliminary Design

Three preliminary GRTP designs of the outboard YC-14 elevator were prepared. One of the designs, a stiffener stabilized panel concept, was selected for further study and evaluation.

Task IV--Manufacturing Development

Manufacturing Development investigations were performed in the areas of laminate consolidation, post-forming methods, bonding and joining methods, chopped fiber and fabric molding, assembly methods, and quality assurance techniques.

Task V--Field Maintenance/Repair Methods

Maintenance and repair included inspection, routine cleaning and restoration, major refurbishment and repair.

THE PROPERTY OF THE PROPERTY O

Task VI--Subcomponent Tooling

The tooling concepts established in Task IV, Manufacturing Development, were used to fabricate the elements and subcomponents in Task VII.

Task VII--Subcomponent Manufacture and Testing

Elements and subcomponents representative of the selected design were fabricated and tested.

Task VIII---Final Design

A final design of the selected concept (Task III) was prepared. The design drawings were sufficiently detailed to supply all manufacturing information required to fabricate the elevator component.

Task IX--Demonstration Article Tooling

The major tools required to fabricate three elevators were designed and fabricated.

Task X--Demonstration Article Fabrication

Three full-scale GRTP YC-14 elevators were fabricated. Processes governing all aspects of manufacturing were developed.

Task XI--Demonstration Article Testing

Two elevators were tested. The first elevator was tested initially to determine torsional and bending stiffnesses. It was then prooftested and then cyclic loaded for four lifetimes. The part was then loaded to destruction to determine residual strength. The second was tested to determine torsional and flexural stiffness, and then it was loaded to failure.

Task XII--Cost and Payoff Analysis

A detailed cost analysis was made to determine the cost of the GRTP elevator for a 300-aircraft producton run. This analysis was developed from cost tracing data obtained during the course of the program. These costs were compared to production costs of the existing aluminum design.

Task XIII--Eraphite/PKXA Thermoplastic Structural Element Evaluation

A comparison was made between the structural integrity of PKXA graphite reinforced thermoplastic (GRTP) and P-1700 GRTP. Critical YC-14 elements made of PKXA GRTP were fabricated and tested. The results from these tests were compared to equivalent data obtained from polysulfone GRTP composites. Fabrication cost comparisons determined that PKXA parts would be produced at the same costs as polysulfone composite parts.

2.0 RESIN AND FIBER SELECTION/EVALUATION

Several samples of developmental thermoplastic prepregs (Table 1) were obtained and evaluated for the purpose of obtaining a satisfactory commercial prepreg for use on this program. The materials finally selected were Hercules' 3004 (A-S/P-1700) unidirectional tape and Hexcel's 23 x 24 eight Harness satin fabric/P-1700 prepreg. Laminates of these materials were fabricated and tested. Figure 1 shows the effect of temperature on their flexural strength and Figure 2 on flexural modulus. Figure 3 shows the effect of temperature on interlaminar shear, and Figures 4 and 5 show the effect of temperature on their tensile strength and tensile modulus. Additional property data for the fabric material is shown in Table 2 and for tape in Table 3.

The graphite fabric prepreg was selected as the primary reinforcing material because it simplified lay-up, was easier to handle and was a more reproducible and uniform prepreg.

Two molding compounds were selected for manufacturing studies. These materials were Fiberite's RTP 1387 polyphenylene sulfide/graphite and RTP 907 polysulfone/glass molding compounds. The vendor designated properties of the PPS material are shown in Table 4.

Table 1. Thermoplastic Prepregs

- 1) HERCULES 3004A-S 3" WIDE TAPE
- 2) DUPONT A-S/P-1700 POLYSULFONE 6" WIDE TAPE
- 3) HEXCEL/T300 181 GRAPHITE FABRIC/P-1700
- 4) FIBERITE/T300 181 GRAPHITE FABRIC/P-1700
- 5) U.S. POLYMERIC T-300/P-1700 POLYSULFONE 12" WIDE TAPE




Figure 1. Effect of Temperature on Flexure Strength — Graphite/polysulfone Composites




Figure 2. Effect of Temperature on Flexure Modulus




Figure 3. Effect of Temperature on Interlaminar Shear




Figure 4. Effect of Temperature on Tensile Strength




Figure 5. Effect of Temperature on Tensile Modulus

Table 2. Graphite Fabric/P1700 Average Test Data

TEST	TEST	COMPRESSION		FLEXURE		ILS	TENSILE	
(DEGREES)	TEMP.	ULT STRESS PSI X 10 ³	MODULUS PSI X 10 ⁶	ULT STRESS PSI X 10 ³	MODULUS PSI X 10 ⁶	PSI X 10 ³	ULT STRESS PSI X 10 ³	MODULUS PSI X 10 ⁶
0	RT	56.0	9.2	128.3	7.7	6.5	77.1	10.2
0	180°F			114.8	7.1		•	•
0	300°F	36.2	10.6	88	7.2	3.5	61.4	10.4
90	RT			96.7	7.7	-	•	-
90	180°F	·		80.0	7.7	•	•	•
90	300°F			66.4	6.7	•	•	•

181 STYLE GRAPHITE FABRIC (HMF)/P1700 RESIN LAMINATE.

Table 3. P1700/A-S Tape Laminate Properties

				-		
COMPRESSION STRENGTH/MODULUS - TAPE LAMINATES						
LAMINATE	TEST DIR.	TEST	+70 ⁰ F	+180 ^o F	300°F	
0º LAMINATE	၄၁	STR.	151,300	102,600	86,200	
		E	15.6	16.1	13.1	
0º LAMINATE	90	STR.	20,500	15,800	10,500	
		E	1.07	1.03	0.97	
±45 LAMINATE	00	STR.	21,000	16,200	12,600	
		E	2.17	2.04	1.48	
	FLEX	JRE PROPERTIE	S - TAPE LAMIN	NATES		
[0 - 90]	0 ₀	STR.	168,000	141,000	113,600	
		E	11.3	10.3	10.0	
[±45°]	00	STR.	40,000	33,800	24,800	
		E	2,0	1.74	1,85	

Table 4. Properties of Polyphenylene Sulfide Graphite Fiber Reinforced Molding Compound

COMPOUND PROPERTIES	AVERAGE	VALUES			
Color		ick			
Injection Pressure, PSI	15-2	0000			
Injection Cylinder Temp., °F.	575	-650			
Mold Temp., °F.	100	-350			
PROPERTIES OF INJECTION MOLDED SPECIME	NS				ASTM
	BASE	RTP	RTP	RTP	TEST
PERMANENCE	RESIN	1323	1385	1327	METI:00
Carbon Graphite Fiber, %	0	20	30	40	
Specific Gravity	1.3	1.38	1.42	1.46	D-792
Molding Shrinkage, in/in, 1/2" Section	0.010	0.0015	0.001	0.0005	D-955
¾" Section	0.009	0.002	0.001	0.0000	
Water Absorption, %, 24 hrs. @ 23° C.	0.02	0.02	0.02	0.02	D-570
MECHANICAL					
Impact Strength, IZOD, Notched 1/4"	0.4	0.2	1.2	1.2	D-256
Unnotched ¼"	1.8	3.0	4.0	4.0	U-200
Tensile Strength, PSI	9500	22000	4.0 25000	26500	D-638
Tensile Elongation. %	1.6	0.75	0.5		
Tensile Modulus, PSI X 104	0.63	2.5	3.7	0.5 4.5	D-636 D-636
Flexural Strength, PSI	14000	27000	3.7 31000	4.5 34000	D-790
Flexural Modulus, PSI X 104	0.55	27000	2.5	3.5	D-790
Compressive Strength, PSI	16000	24000	2.5 26000	3.5 27000	
Hardness, Rockwell R	120	122	123		D-695
	120	122	123	123	D-7 6 5
ELECTRICAL					
Dielectric Strength, VPM, S/T	380	NA*	NA*	NA*	D-149
Dielectric Constant, 1 MC, Dry	3.1	NA	NA	NA	D-150
Dissipation Factor, 1 MC, Dry	0.0009	NA	NA	NA	D-150
Arc Resistance, Seconds	20	NA	NA	NA	D-495
Volume Resistivity, Ohm CM	1014	75	40	30	D-257
THERMAL					
Deflection Temp., °F., @ 264 ?S:	275	500	500	500	D-648
@ 66 PSI	300	500+	500+	500+	
Flammability	SE	SE	SE	SE	D-635
Flammability, UL Sub. 94, 1/4"	VEO	VEO	VEO	VEO	D-033
Coefficient of Linear Thermal		1.0	160	AFO	
Expansion, in/in/°F, X 10 3	2.7	1.1	0.89	0.78	D-696
Thermal Conductivity, BTU/Hr./	4.7	4.4	V.07	U./8	D-830
Ft ² /°F./in.	2.0	2.1	2.5	3.3	C-177

DATA SOURCE: FIBERITE CORPORATION

3.0 CONCEPTUAL DESIGN/CONCEPT EVALUATION

3.1 INTRODUCTION

Concept design and evaluations were performed to determine the cost trends between graphite structural components fabricated using epoxy resin systems and those using thermoplastic resin systems. These studies also showed structural weight savings provided by the advanced composite materials systems.

Several components as shown in Table 5, from the YC-14, a large transport aircraft, the Firebee missile, and Compass Cope drone were selected for study. All of them had been previously designed with fiberglass or aluminum alloys. New designs were developed using graphite/epoxy and graphite/ thermoplastic construction. The resin systems were considered to have a maximum use temperature of 275°F. The graphite-epoxy and graphite-polysulfone designs for each component were basically the same with slight variations made to accommodate the unique characteristics of each material. The weight therefore of each component using the two advanced composite systems was the same. However, the costs of fabricating the components with the two advanced composite materials systems were quite different since different modes of construction were used. A summary of the cost factors and assumptions used in the cost studies is shown in Table 6.

TO SELECTION OF THE PROPERTY O

3.1.1 COST PROCEDURE

Cost procedures were used that were based on cost histories from actual component fabrication. They were initially established for graphite-epoxy composite parts but with some modifications were also used for AFRTP composites. The resulting method has proven to be accurate for preliminary cost estimates.

To obtain fabrication time for producing detail parts the number of plies or precompacted laminates and the areas for each part were determined. These two values were multiplied to obtain the square foot-plies. This value times the

Table 5. Conceptual Design and Evaluation Components

STUDY COMPONENTS	APPLICATION
BODY	YC-14
	LARGE TRANSPORT
	BQM-34E FIREBEE DRONE
WING (YC-14)	STIFFENED LAMINATE
	HONEYCOMB
HORIZONTAL STABILIZER	YC-14
	COMPASS COPE

Table 6. Cost Factors and Assumptions

MATERIAL COSTS:

GRAPHITE/EPOXY

GRAPHITE/POLYSULFONE (PRE-COMPACTED)

\$-GLASS/EPOXY OR S-GLASS/POLYSULFONE

ADHESIVE

HONEYCOMB CORE

\$25/lb

\$12/lb

\$1/ft²

\$ 0.03/in³

LABOR COSTS

\$30/hr

LOSS FACTORS

PARTS SCRAPPAGE FACTOR — 5% FOR Gr/E — 1% FOR Gr/Ps
MATERIAL LOSS (INCLUDES RESIN, SOLVENT AND STORAGE
LOSSES AND CUTTING SCRAPPAGE BUT NOT OVERAGE
MATERIAL) — 30% FOR Gr/E — 15% FOR Gr/Ps

LABOR FACTORS

MANUFACTURING ENGINEERING

QUALITY CONTROL

TOOL MAINTENANCE

TOOL DESIGN

0.35 x Production hr.

0.15 x Production hr.

0.15 x Production hr.

0.30 x Tool Fab hr.

LEARNING FACTORS

85% LEARNING CURVE FOR BOTH THERMOSET AND THERMOPLASTIC SYSTEMS

10 UNITS = 7.116 x Unit 1 100 UNITS = 43.754 x Unit 1 factor (mhr/sq ft-ply) provided the manhours required per part and, when all were added together, gave the total parts manhour cost. The curves used to select the above factor are shown in Figure 6. The figure relates mhr/sq ft-ply to the area of the part. Four curves were used to irdicate complexity. These curves were developed from actual fabrication experience and are intended to establish the costs of the first production unit.


Assembly time was obtained by multiplying the total area of the parts by a factor mhr/ft^2 as shown in Figure 7. Three curves are shown which indicate complexity of the component. These curves were also based on cost data obtained from actual assembly of composite components.

man or other control by the in Secretarial chieses solvened and Open the control bases and and a second control by

To obtain the total production cost the manhours for each part were added and the total multiplied by a parts scrappage factor. The assembly cost was then added to obtain the production hours. The manufacturing engineering, quality control, and tool maintenance manhours were obtained by factoring these production hours. This total was the value used as the recurring production cost.

The material costs were obtained by adding the cost of the composite to the cost of other materials used such as honeycomb and adhesive. The net composite weight was obtained by adding the sq ft-ply values obtained for each part and multiplying by the proper factor (lb/sq ft-ply). A material loss factor and a part scrappage factor were added to obtain the total composite weight required. A cost per pound value was then used to get the composite cost. Honeycomb cost was determined by finding the cubic inches of core requirement and using a cost per cubic inch factor. The adhesive cost was determined from the area and the cost per unit area.

The tooling costs were obtained using Figure 8 which indicated the relationship of tool area to cost per unit area. Four levels of complexity are indicated. These curves were based on actual tool fabrication data and indicated the shop hours required to fabricate the tool. The design hours required for tooling were obtained by factoring the fabrication hours. The sum of the tool design a d fabrication hours gave the total nonrecurring tooling hours.






Figure 7. Assembly Time




Figure 8. Tooling Time

3.2 YC-14 FUSELAGE BODY SECTION 43

A YC-14 fuselage advanced composite design was developed which uses a honey-comb sandwich shell as the primary load carrying structure. The honeycomb construction incorporated HRH honeycomb and graphite-epoxy or graphite-polysulfone skins. The design utilized large bonded assemblies and a minimum number of frames and bulkheads to reduce the total number of parts. Major assemblies were assembled using mechanical fasteners. Figure 9 shows the structural centerline drawing of this design.

Body section 43 was selected as a representative YC-14 fuselage component for the weight and cost study. Figure 10 shows the details of this section. A detailed weight and cost estimate of the section between Stations 300 and 440 was made and then scaled to obtain the Section 43 estimated weights and costs. Both advanced composite designs were approximately 20 percent lighter than the equivalent aluminum design. The cost estimates comparing graphite-epoxy and the graphite-polysulfone designs are shown in Table 7. As shown, the cost of the graphite-polysulfone design is significantly less by the tenth part and its cost effectiveness continues to improve as production quantities increase.

3.3 LARGE TRANSPORT A/C FUSELAGE PANEL

A typical sidebody panel for a large transport A/C was studied to compare the costs between a graphite-epoxy design and a graphite-polysulfone design. The all-aluminum design had conventional hat stringer stiffened skin and zee section frames. The advanced composite design described in Figure 11 has a graphite laminate skin stiffened by graphite "T" stringers, three composite rings, and two aluminum frames. Graphite pultrusions reinforced the outstanding legs of the stringers. The ring stiffeners are made of HRP core with graphite laminate face skins. Graphite laminate shear clips attach the aluminum frames to the skin.

Both advanced composite designs were approximately 16 percent lighter than the equivalent aluminum design. The cost estimates comparing graphite-epoxy and graphite-polysulfone designs are shown in Table 8. As shown, the graphite-polysulfone components were more cost effective than the graphite-epoxy components after only a few of the assemblies were produced.






Figure 9. YC:14 Fuselage Structure Centerline Diagram



View B




AND THE PROPERTY OF THE PROPER

Figure 10. Fuselage Section 43 - Details

Table 7. Fabrication Costs for Advanced Composite Designs YC-14 Fuselage Body Section 43

ADVANCED COMPOSITE MATERIAL	NO. OF UNITS	PRODUCTION HRS.	MATERIAL DOLLARS	TOOLING HRS.	TOTAL COST DOLLARS
GRAPHITE/EPOXY	1	14,877	83,418	23,904	1745,848
	01	105,865	830,418	23,904	ter v
	100	650,928	8,304,180	23,904	28 */
GRAPHITE/POLYSULFONE	Ļ	990'9	71,242	39,884	1,449,742
	01	43,166	712,420	39,884	3,203,910
	6	265,412	7,124,200	39,884	16,283,072






Table 8. Fabrication Cost for Advanced Composite Designs Large Transport A/C Fuselage Panel

ADVANCED COMPOSITE MATERIAL	NO. OF UNITS	PRODUCTION HRS.	MATERIAL DOLLARS	TOOLING HRS.	TOTAL COST DOLLARS
GRAPHITE/EPOXY	1 10	1,425 10,140	24,520	1,310 1,310	84,502
	100	62,349	245,200	1,310	2,154,970
GRAPHITE/POLYSULFONE	1	961	2,099	2,184	96,449
	10	86838	20,990	2,184	291,650
	901	42,048	209,900	2,184	1,536,860

的一个人,我们是是一个人,我们是是一个人,我们是是一个人,我们是是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们

3.4 FIREBEE DRONE CENTERBODY SECTION COMPONENTS

The XBQM-34E supersonic Firebee drone graphite-thermoplastic panel and door component designs were developed, fabricated, and delivered to NADC for ground testing under NADC Contract NG2269-74-C-0368, "Development of a Low Cost Graphite Reinforced Composite Primary Structural Component." The location of the components on the drone are shown in Figure 12 and their design details are shown in Figures 13 and 14. Figure 15 is a photograph of the actual delivered hardware.

Element and subcomponent tests confirmed the practicality and structural performance of the design concept. Weight saving for the retrofitted graphite-thermoplastic components was 5 percent.

Estimates were made of the costs for producing these components using graphite-epoxy and graphite-polysulfone. Table 9 shows a comparison of these two cost estimates. As shown, the graphite-polysulfone components are more cost effective than the graphite-epoxy components after the first few production parts.

3.5 YC-14 STIFFENED LAMINATE WING BOX

A multi-rib skin stringer wing box design was developed for the YC-14 as shown in Figure 16. The box was designed to be fabricated as a single component from tip to tip. It consisted of upper and lower stringer stiffened graphite laminate skins, a front and rear spar, and 66 ribs. The spars were a graphite laminate construction and the ribs HRH honeycomb core with graphite laminate face skins. The spars and ribs are detailed in Figure 17. The skin stringer consisted of an HRH honeycomb core filler and graphite pultrusions overwrapped with $\pm 45^{\circ}$ graphite laminate plies. The honeycomb is used to maintain a constant stringer cross section as the pultrusions are tapered along the length of the wing box. The upper skin panel stringers incorporate four pultrusions, the lower skin panel stringers two pultrusions. Details of the stringers are shown in Figure 18. The wing box design was sized to have the same bending and torsional stiffness as the YC-14 aluminum box. The surface panels were limited to $\epsilon_{\text{max}} = 0.0044$ in./in. at ultimate load.






Figure 12. Firebee Drone Profile and Selected G r /Ps Components



نى

The second section of the second

Figure 13. Prototype Gr/Ps Component Design Concept Details



os la tratata S-da




Figure 14. Skin Installation — Centerbody Section




Figure 15. Delivered GRTP Components For The Fire: Drone Center Body Section.

Fubrication Costs for Advanced Composite Designs Firebee Drone Body Component Table 9.

in which is not the seal of the same of the same

lable 3. Full teation Costs for Attracted Composite Designs Firebee Divine Body Components	I O I CI	יים המוויחם חפיו	esigns ruebee t	ייטי שוטיי	anponant
ADVANCED COMPOSITE MATERIAL	NO. OF	PRODUCTION	MATERIAL	TOOLING	TOTAL COST
	UNITS	HRS.	DOLLARS	HRS.	DOLLARS
GRAPHITE/EPOXY	100	718 5,109 31,415	620 6,200 62,000	624 624 624	40,880 178,199 1,023,181
GRAPH!TE/POLYSULFONE	1	396	527	1,131	46,337
	01	2,818	5,270	1,131	123,738
	001	17,327	62,700	1,131	606,428





Figure 16. YC-14 Wing Structure Diagram

TAXABETUSTA.

THE PROPERTY OF THE PROPERTY O




The second second

Figure 17. YC-14 Stiffened Laminate Wing Concept

SOUTH SOUTH

TYP RIB DETAILS

A: UPPER PANEL STRINGERS



THE CONTROL OF THE CO




Figure 18. Stiffened Laminate Stringer Configurations

A weight estimate of the design is summarized in Table 10. As shown, the stiffened graphite laminate wing box is approximately 25 percent lighter than the equivalent aluminum design.

Estimates were made of the costs for this component fabricated using graphite-epoxy and graphite-polysulfone laminate and pultrusion material. Table 11 compared these estimates and shows the graphite-polysulfone is more cost effective by the tenth production component.

3.6 YC-14 HONEYCOMB WING BOX

A multi-spar-rib honeycomb wing box was developed for the YC-14 as shown in Figure 19. The box was designed to be fabricated as a single component from tip to tip. It consists of upper and lower skin panels, a front and rear spar, two intermediate spars, and twenty-four ribs. These are all HRH honeycomb parts with graphite laminate face skins. The intermediate spars are continuous members while the ribs act as intercostals between spars. The wing box design was sized to have the same bending and torsional stiffness as the YC-14 aluminum box. The surface panels were limited to $\epsilon_{\text{max}} = 0.0044$ in./in. at ultimate load.

A weight estimate of the design was made and summarized in Table 12. The honeycomb wing box is approximately 29 percent lighter than the equivalent aluminum design.

Estimates were made of the costs for fabricating this component using graphite-epoxy and graphite-polysulfone face skins. Table 13 compares these two cost estimates. As shown, the graphite-polysulfone components are most cost effective than the graphite-epoxy components after the first few production parts. The graphite-epoxy component costs were based on data obtained from a 6-foot box section fabricated under Boeing in-house funding.

3.7 YC-14 HORIZONTAL STABILIZER

YC-14 horizontal stabilizer advanced composite designs were developed for evaluation. The stabilizer had a 17-1/2 ft. semi-span with a root chord of 5-1/2 feet and a tip chord of 3 feet. The designs were based on a multispar


Table 10. Wing Box Weight Summary—Stiffened Laminata Design (Weight in Lbs.)

ITEM	AL	STIFFENED GRAPHITE	Gr/AL
UPPER PANEL	4211	3354	.80
LOWER	4214	3182	.775
SPARS	1540	943	19.
RIBS	1974	1482	.75
TOTALS	11,939	8961	.75
25% WEIGHT SAVING	r SAVING		

Table 11. Fabrication Costs for Advanced Composite Designs-YC-14 Stiffened Laminate Wing Box

ADVANCED COMPOSITE MATERIAL	NO. OF	PRODUCTION HRS.	MATERIAL	TOOLING HRS.	TOTAL COST DOLLARS
GRAPHITE/EPOXY	1000	31,970 227,498 1.398,815	288,150 2,881,500 28.815,000	24,162 24,162 24,162	1,972,110 10,431,315 71,504,319
GRAPHITE/POLYSULFONE	1001	20,225 143,921 884,925	246,000 2,460,000 24,600,000	44,158 44,158 44,158	2,177,490 8,102,373 52,472,479

THE CONTROL OF THE PROPERTY OF



では、100mmので

Figure 19, YC-14 Honeycomb Wing Concept

NOT THE PROPERTY OF THE PROPER

Table 12. Wing Box Weight Summary—Honeycomb Concept (Weight in Lbs.)

		HONEYCOMB	Gr/AL
ITEM	A	GRAPHITE	
UPPER	4211	2975	.71
PANEL			
LOWER	4214	3052	.72
PANEL			
SPARS	1540	943	19:
RIBS	1974	1482	.75
TOTALS 11,939	11,939	8452	.71
29% WEIG	29% WEIGHT SAVING	אפ	

Table 13. Fabrication Costs for Advanced Composite Design-- YC-14 Honeycomb Wing Box

ADVANCED COMPOSITE	NO. OF UNITS	PRODUCTION HRS.	MATERIAL DOLLARS	TOOLING HRS.	TOTAL COST DOLLARS
GRAPHITE/EPOXY	100	24,945 177,509 1,091,443	245,870 2,458,700 24,587,000	24,344 24,344 24,344	1,724,540 8,514,280 58,060,625
GRAPHITE/POLYSULFONE	- 01 001	13,159 93,639 575,759	211,981 2,119,810 21,198,100	42,406 42,406 42,406	1,878,930 6,201,173 39,743,046

(4) concept and incorporated several full and partial ribs. A centerline diagram of the stabilizer is shown in Figure 20. Both the covers and the ribs were stiffened with beads. The spar webs were stiffened with "Tees" made of two back-to-back angles. Details of a typical spar/rib intersection are shown in Figure 21. The cover panels, spar and rib webs were all made of graphite/polysulfone fabric oriented at +45°.

The weights of both the Gr/E and GR/Ps designs were determined. They were compared to the existing aluminum design and estimated to be approximately 35 percent lighter.

Cost studies were also performed which compared the fabrication cost of graphite-epoxy components with graphite-polysulfone components. The results obtained were consistent with the results obtained in previous cost studies.

Because of higher tooling cost the first unit production cost of a YC-14 horizontal stabilizer using graphite-polysulfone was higher than the design using graphite-epoxy. But, because the graphite-polysulfone design required fewer production hours, it could be produced at a lower net cost by the production of the tenth unit. Table 14 summarizes the data developed while evaluating YC-14 horizontal stabilizer production costs.

3.8 COMPASS COPE HORIZONTAL STABILIZER

A Compass Cope advanced composite horizontal stabilizer design was developed which used a honeycomb stabilized skin. The existing design utilizes fibergless sandwich construction as shown in Figure 22. The stabilizer was 180 inches long and 20 inches between its forward and rear spars as shown in Figure 23. Typical details of the composite design are shown in Figure 24. The upper and lower panels were stabilized with 1/4 in. thick, 3 lb Nomex core. The face skins were 0/±45/90 graphite laminates. The rib webs are also stabilized with Nomex core.

The weights were determined for both the Compass Cope fiberglass honeycomb design and the graphite designs developed in this study. This data showed that the composite designs (graphite-epoxy and graphite-polysulfone) were 36 percent lighter than the fiberglass honeycomb design.





Figure 20, YC-14 Horizontal Stabilizer Centerline Diagram



Add to make the bather of the water of the

The same of the sa

Figure 21. Typical Spar/Rib Attachment

Table 14. YC-14 Advenced Composite Horizontal Stabilizer Cost Estimate

ADVANCED COMPOSITE MATERIAL	NO. OF UNITS	PRODUCTION HOURS	MATERIAL DOLLARS	TOOLING HOURS	TOTAL COST DOLLARS
GRAPHITE/EPOXY	ı	299'8	46,926	7,742	536,076
	5	90,936	469,280	7,742	2,529,550
	Š	374,666	4,692,600	7,742	16,164,825
GRAPHITE/POLYBULFONE		6,050	40,015	11,726	673,295
	2	43,062	400,150	11,726	2,043,484
	0 01	264,712	4,001,500	11,726	12,294,631




Figure 22. Compass Cope Material Systems





Figure 23. Compass Cope-Horizontal Stabilizer Composite Design

THE PROPERTY OF THE PROPERTY O



A. 1. .

÷

A STATE OF THE SECOND WAS A STATE OF

Figure 24. Compass Cope Horizontal Stabilizer Details

Studies were also performed to determine the relative costs between the graphite-epox; and graphite-polysulfone designs. A summary of this data is shown in Table 15. As shown, the graphite-polysulfone design is more cost effective by the production of the tenth unit. The first unit is more expensive because of higher tooling cost. The significantly lower production hours required for producing the graphite-polysulfone parts amortizes the difference in tooling in a manner which makes the tenth production part more cost effective than the equivalent graphite-epoxy part.

Another cost study was made in which the cost of producing the fiberglass/epoxy honeycomb design was completed to the graphite-polysulfone design. In this study the fiberglass/epoxy material costs were based on aerospace quality material of \$12/lb and the graphite-polysulfone at todays cost of \$65/lb. The cost data is summarized in Table 16. As shown, the low production cost of the graphite-polysulfone design offsets the increase in material and tooling cost by the fabrication of the tenth part.

3.9 CONCLUSIONS

Seven aircraft and missile structural components were evaluated in this program (Table '. The evaluation compared advanced composite component designs with existing aluminum or fiberglass designs. In all cases the results showed that the composite designs were lighter than the more conventional designs. The weight savings were from 5 percent for replacement body panels on the Firebee Drone to 36 percent provided by a new composite design of the Compass Cope's horizontal stabilizer.

One of the major objectives of this study was to obtain the relative costs between producing components utilizing graphite-epoxy materials and graphite-polysulfone. The study results consistently showed that using an 85% learning curve, the graphite-polysulfone parts were more cost effective by the production of the tenth unit. The tooling costs were higher for the graphite-polysulfone because of higher process temperatures and pressures. This additional cost was offset by the lower production costs, thereby producing a lower cost part by the production of the tenth unit. In general, the first unit cost of a thermoplastic component was 14 percent higher than the epoxy component. By the production of the tenth unit, the cost of thermoplastic parts averaged 33 percent less than the epoxy parts.

Table 15. Compass Cope Advanced Composite Horizontal Stabilizer Cost Estimate

ADVANCED COMPOSITE MATERIAL	NO. OF UNITS	PRODUCTION HOURS	MATERIAL	TOOLING	TOTAL COST DOLLARS
GRAPHITE/EPOXY	-	1,068	1,213	810	57,553
	9	00 0	12,130	810	264,426
	100	46,730	121,300	810	1,547,478
GRAPHITE/POLYSULFONE	-	775	1,060	1,690	75,010
	01	5,515	10,600	1,690	226,747
	100	33,909	106,000	1,690	1,173,980

Table 16. Compass Cope Horizontal Stabilizer Cost Estimate - Glass/Epoxy and Graphite/Polysulfone

ADVANCED COMPOSITE MATERIAL	NO. OF UNITS	PRODUCTION HOURS	MATERIAL DOLLARS	TOOLING HOURS	TOTAL COST DOLLARS
GLASS/EPOXY	-	1,068	909	810	56,940
(\$12/LB.)	5	2,600	000'9	810	258,296
	8	46,730	60,000	810	1,486,178
GRAPHITE/POLY JULFONE	,-	775	2,760	1,690	76,710
(\$65/LB.)	5	5,515	27,600	1,690	243,747
	5	33,909	276,000	1,690	1,343,980

AN TO THE PROPERTY OF THE PROP

4.0 MANUFACTURING DEVELOPMENT

A series of studies were performed to evaluate graphite thermoplastic processing methods. The areas of study included laminate consolidation, post-forming bonding and joining methods and chopped fiber molding fabrication. A summary of the areas investigated is shown in Table 17.

4.1 CONSOLIDATION

Four laminate consolidation methods were investigated. They were accomplished by press, autoclave, pultrusion and roll-forming.

4.1.1 Press Consolidation

Press lamination studies were performed which resulted in a two-hour cycle for a 4 ft² laminate (0.5 hr/ft²). The time per unit area was dependent upon the capacity and capability of the press utilized. If the press had rapid heating or cooling capability, the cycle time could have been reduced. The two-hour cycle was based on a part/mold assembly heatup rate of 10° F/min from room temperature to $+650^{\circ}$ F and cooldown to $+100^{\circ}$ F. The cycle time could have been reduced to 1.25 hr if the part/mold was preheated to $+350^{\circ}$ F in an oven or other facility prior to insertion in the press and then molded at 600° F/200 psi, and removed at $+300^{\circ}$ F on the cooldown cycle.

Consolidation costs could have been further reduced by laminating multi-sheets at one time using a separator ply between layers. This technique would have increased the cycle time due to heat flow but the time per ft² of laminate would have decreased signifiantly as shown in Table 18. This table assumed three sheets were molded simultaneously.

Figures 25 and 26 show the cross section of a press consolidated unidirectional laminate and a 181-style fabric laminate respectively.

Table 17. Task IV-Manufacturing Development

LAMINATE CONSOLIDATION: o ROLL LAMINATION o PULTRUSION o AUTOCLAVE LAMINATION o PRESS LAMINATION **POST-FORMING METHODS:** o PRESS (MATCHED-DIE) o AUTOCLAVE MOLDING o VACUUM FORMING o PULTRUSION o FUSION BONDING/JOINING METHODS o ADHESIVE BONDING o MECHANICAL FASTENING o INJECTION MOLDING CHOPPED FIBER MOLDING: o MATCHED-DIE o FUSION **ASSEMBLY METHODS:** o ADHESIVE BONDING QUALITY ASSURANCE TECHNIQUES:

Table 18. Processing Time for Consolidation

		HR/FT ²
PRESS	- SINGLE SHEET	.5
	- SINGLE SHEET W/PRE-HEAT	.32
	- MULTIPLE SHEET	.10
AUTOCLAVE	- SINGLE SHEET	0.125
	- MULTIPLE SHEET	0.041
PULTRUSION	·	2-6 INCHES/min.
ROLL-FORMING	•	Not established




Figure 25. Press Consolidated Unidirectional Laminate




Figure 26. Press Consolidated 181 Style Graphite Fabric Laminate

on her and the second state of the second second

4.1.2 Autoclave Consolidation

Autoclave laminating has an advantage because large areas can be laminated at one time. The cycle time on Boeing's small autoclave (4 ft dia x 8 ft long) was 4 hr. This included bagging and debagging and allowed for a heat rise of 10° F/min with a 30 min hold at temperature followed by a 12° /min cooldown to room temperature. Laminating 32 ft² resulted in costs of 0.125 hr/ft² to 0.041 hr/ft² when three sheets were laminated simultaneously. This low cost consolidation was accomplished without major tooling expense.

4.1.3 <u>Pultrusion Compaction</u>

Existing graphite-epoxy pultrusion equipment was modified to provide higher temperature and pressure capabilities needed for making graphite thermoplastic pultrusions. The existing microwave pultrusion chamber was used as a first stage preheat in series with a second stage where resin softening and compaction occurred. The new second-stage cure chamber consisted of 30-in.-long electric conduction heated chrome steel platens, which were hydraulically actuated with a 200 psi pressure facility. The first 15 inches of the platen was heated while the remaining 15 inches were force-air cooled. The pultrusion puller system was modified to provide increased pulling capabilty. A flow chart of the thermoplastic pultrusion facility is shown in Figure 27.

THE STATES OF TH

Three basic polysulfone/graphite pultruded shapes were fabricated in these studies. These were 3-in. wide solid laminates, 1-in. x 1-in. angles, and 0.040-in. x 3-in. wide sandwich. Three-inch wide tape, 0.005-in. thick was used for making the solid laminates. Eleven- and eighteen-ply laminates were made at speeds varying from 1/2 in. to 6 in. per minute. The best results were obtained at temperatures of 600°F and pressures of 200 psi at pull speeds of 2 in. per min. Angle sections were also made using 12 plies of 0.005 inches thick tape. The best results were obtained using approximately the same process parameters described above. The above sections were also made using polysulfone impregnated woven fabric. This form of material proved to be much more difficult to handle since it would neck down when pulled through the dies. This was solved by using a supporting teflon fabric on both sides of the laminate.




Figure 27. Thermoplastic Pultrusion Facility

THE PERMIT SHEET S

Sandwich panels were made using woven fabric face skins and polyimide core. Although the feasibility of producing sandwich sections was established, the finished parts had insufficient peel strength between the face skins and the core due to inadequate adhesive filleting. This characteristic could be improved by using face skin material with a polysultone resin rich surface on the core interface for a more compatible adhesive system. A photograph of the three sections pultruded is shown in Figure 28. These parts were sectioned; inspection showed them well compacted and free of voids.

Flat platens with side bar inserts were used for producing the flat laminate pultrusions and two-part dies for the shape pultrusions. Ceramic platens or dies were used in the first stage (MW heated) and chrome plated steel in the second stage (electric cartridge) heater.

The studies demonstrated the feasibility of producing pultruded graphite polysulfone structural shapes. Future potential improvements include extruded sandwich panels whose face peel strengths were low but which could be remedied by using prepreg that was resin rich on the core side; or by providing an adhesive system which would provide better filleting and one that would be compatible with the short processing times in the pultrusion equipment. This could be either a thermoset or a thermoplastic adhesive system. The pultruding equipment could also be further improved by using longer platens which would allow an increase in pull force by reducing platen friction. This also could be accomplished by developing an air bearing platen.

4.1.4 Roll Forming Compaction

A survey was performed to find a commercial source with the equipment and capability to perform continuous roll compaction. Several companies were contacted which had adequate rolling equipment but lacked the temperature capability since they were steam heated. This effort was discontinued.

4.2 POST FORMING

The post-forming methods investigated were (a) press match die, (b) autoclave, (c) vacuum forming, and (d) pultrusion forming which was discussed in the previous section and therefore will not be covered here.




Figure 28. Graphite Thermoplastic Pultruded Sections

4.2.1 Press Match Die Post Forming

Several parts were made by post forming in a press with match dies. This technique consists of preheating a consolidated laminate and then placing it in warm dies located in a press for forming. The consolidated material is heated to approximately $500^{\circ}F$ while the die is restricted to the 300° to $325^{\circ}F$ temperature range. The die tends to cool the part below the polymer softening point $(345^{\circ}F)$ after forming. This method will produce typical parts in a time span of 6 to 8 minutes which is considered highly acceptable for production. The channel shown in Figure 29 was produced by this procedure. The eight-ply laminate used to produce the channel was preheated, placed over a female metal die, and then pressed to its final shape with a silicone plug. The silicone plug enabled the fabric to fill in all corners of the mold with uniform pressure resulting in a well compacted high tolerance part. Figure 30 shows a double contoured part that was successfully produced by this method.

4.2.2 Autoclave Post Forming

Several parts were successfully post formed in an autoclave in this program. The process is similar to the press die forming except autoclave pressure is used to form the part. The cycle time in the autoclave was approximately 3.0 hours which was less than used for consolidation because the hold time is not required. Also, the forming temperature was reduced since parts are heated to slightly above the softening temperature. The autoclave post forming cycle is significantly less time than the cure cycle for epoxy parts and therefore has economical advantages for producing large composite parts. Costs are saved in shorter cycle times thus providing more facilities usage; less labor costs and on some cases less total energy usage.

Figures 31 and 32 show two parts that were formed by using autoclave pressure. In Figure 31, a web is shown which was formed out of graphite-polysulfone tape oriented at $(0^{\circ},90^{\circ})$. Figure 32 shows a shear web formed out of fabric using the same tooling. Both parts were carefully examined and no delaminations or serious fiber distortions were found.




Figure 29. Press Match-Die Molded Post Formed Channel



Figure 30. Press Molded Shapes-Silicone Plug Mold




Figure 31. Shear Web Molded From (0/90)_S Graphite Tape Composite




Figure 32. Shear Web Molded Form Graphite Fabric

4.2.3 <u>Vacuum Forming</u>

Vacuum forming proved to be a cost-effective method of making formed parts. Figure 33 shows shear-web 0.040 in. thick which was formed from 0^0 to 90^0 sheet stock made from tape. A graphite fabric laminate part is shown in Figure 34. Both parts were vacuum formed using a 10-minute cycle. Figure 35 shows a schematic of the vacuum forming equipment. It consists of three stages. The laminate was loaded in Zone 1 where it was then moved to Zone 2 which consists of an oven. The laminate was heated with radiant lamps to 550 to 600^0 F and then moved to Zone 3 where the actual forming takes place. The hot laminate was formed over an aluminum tool with vacuum pressure. When full vacuum was on the part, the forming cavity was pressurized with plant air (80 psi) to consolidate the part. Figure 36 shows a schematic of the forming chamber. The laminate was then cooled and removed as shown in Figure 37.

Time studies on a production basis showed parts could be produced on a 10-12 minute cycle. The main factor governing the cycle time was part thickness and the time associated with bringing the laminate up to forming temperature.

Vacuum forming provides extremely accurate and reproducible parts. The process could be improved by increasing the auxiliary air pressure from 80 to 150 psi. This increased air pressure produces a very high quality structural laminate in all configurations.

4.3 BONDING/JOINING METHODS

Three methods of load transfer were investigated. They were by fusion bonding, adhesive bonding, and mechanical attachments.

4.3.1 Fusion Bonding

Fusion joints were formed by using heat and prescure to fuse the Lomposite matrix material. A previous contract (NA3C Contract No. N00019-72-C-0526) demonstrated that lap bond strengths in excess of 8,000 psi could be developed in unidirectional graphite P1700 composites. This value was obtained by fusion at 550°F and 200 psi. The efforts in this program were directed toward forming fusion bonds using techniques requiring less pressure and more conducive to multi-part production.




Figure 33. Vacuum Formed Shear Web (0/90) $_{\mathcal{S}}$ Sheet Stock




Figure 34. Vacuum Formed Shea. Web Graphite Fabric





Figura 35. Chemithon Thermoforming Machine



GRTP LAMINATE

- MALE VFM $\Theta \Theta \Theta \Theta$
- VACUUM CAVITY
- PRESSURE CAVITY (100 PSI MAX.)
- SILICONE RUBBER SHEET (PRESSURE SIDE—NO HOLES) **(**9)
- SILICONE RUBBER SHEET (VACUUM SIDE-VAC. PASS-THRU HOLES) **@**
- CLAMFING FRAME-ON OVEN SHUTTLE (b)

Figure 36. Vacuum Forming Chamber - Schematic

THE PROPERTY OF THE PROPERTY O




Figure 37. Graphite Thermoplastic Vacuum Forming-Part Removal

One approach investigated placed resistance wires at the bond interface and applied a potential across the joint interface. As a result the heated wires softened the polysulfone which fused and formed the joint. Figure 38 shows a polysulfone adhesive film 2.5 mils thick with the resistance wires embedded. Figure 39 shows a joint made with this type of film and minimum contact pressure. Lap shear values in the range of 1,400 psi were obtained with specimens made from this joint. However, the interface in this joint had only 25 percent of the area fused. The wire (28 ohms/ft) did not generate enough uniform heat. Based on this data it seemed likely that if total area fusion was obtained then shear strengths in the range of 4,000 to 5,000 psi were possible. Figure 40 shows a cross-section of the fused area in the joint. Some voids are evident but in general excellent fusion was obtained.

Another series of specimens was made in which stainless steel screen (80 mesh) was used as a resistant heater. This type of adhesive screen is shown in Figure 38. This joint was formed in 90 seconds using a pressure of 10 psi. The composite overheated as shown in Figure 41 but lap shear values of 3,800 psi were obtained. All failures were adhesive at the wire mesh interface. The 80-mesh wire is a very close weave and therefore very little penetration of the screen occurred. Additional joints were made at a lower power setting to prevent overheating the composite. This worked very well but the joint strength was not increased and the failure mode remained the same. Although additional work could not be performed in this program, the resistance wire heating technique proved very promising and warrants further research.

是一次,这一位,我们是一个,我们是一个,我们是一个,我们是一个,我们是一个,我们是一个,我们是一个,我们是一个,我们是一个,我们是一个,我们是一个,我们是一个,我们

Another joining technique that was investigated and proved promising was electromagnetic bonding. With this method, a lap shear value of 3,750 was obtained.

Electromagnetic bonding utilizes the principle of induction heating between two abutting thermoplastic surfaces, to fusion temperature, via a heat-activated electromagnetic adhesive layer. The electromagnetic material at the bonding interface consists of a dispersion of finely divided metal particles in a thermoplastic matrix. When the interface is subjected to a high frequency alternating current, fusion temperature is instantly achieved. Under slight pressure a bond is formed. Figure 42 shows a cross section of a bond that was




Figure 38. Polysulfone Adhesive Films with Self Contained Heating Wires and Screen




Figure 39. Fusion Joint-Resistant Heating Wires




Figure 40. Fusion Joint-Close Up




Figure 41. Fusion Joint-Resistant Heating Screen




Figure 42. Electromagnetic Bonding

formed in a matter of 5 seconds. The joint shows some porosity, indicating more pressure or process refinements are required but the composite-adhesive interface is not discernible. The light particles in Figure 42 are the polycarbonate electromagnetic filler used in the adhesive.

4.3.2 Adhesive Bonding

Several specimes were fabricated and tested to obtain load transfer capabilities for graphite-polysulfone adhesive bonded joints. A toom temperature curing adhesive, Hysol EA 934, was evaluated to obtain data for developing field repair techniques discussed later in this report. The average lap shear values obtained are summarized in Table 19. An elevated temperature $(250^{\circ}F)$ cure adhesive was also tested to obtain data for primary joints in the design of components. This data is also summarized in Table 19. Specimens were also fabricated with tape orientated at (0°) . A summary of this data is shown in Table 20 along with data from other joining methods.

4.3.3 <u>Mechanical Fastening</u>

A study was made to evaluate the effect of die-punching holes in a thermoplastic laminate in contrast to the conventional method of drilling and reaming. Holes 1/4 in. in diameter were die-punched in laminates of three different thicknesses, 0.022, 0.44, and 0.066 in. The laminates were then tested in tension and compared to an unpunched laminate. Similar tests were conducted using a 1/4 in. drilled and reamed hole. The results are shown in Table 21. The punched hole was more effective on the thin laminates (0.022) than the drilled and reamed hole since the drill has a tendency to "bite" into the thin material. The two methods of hole preparation appear comparable on the 0.044 in. thick laminate. With the thicker laminate (0.066 in.), the force to die-punch the material appears to do considerable damage around the hole, resulting in a loss in laminate properties. Figures 43 and 44 show a comparison of a punched and drilled/reamed hole on a 0.066 in. laminate. Subsequent tests determined that a punched hole cleaned by reaming, is similar to a drilled/reamed hole (see Table 22).

Table 19. Adhesive Lap Shear Strengths 2

ADHESIVE	CURE TEMPERATURE deg F	PRESSURE APPLICATION	STRENGTH (PSI)
HYSOL EA 934	R.T.	VACUUM BAG	2025
HYSOL EA 934	R.T.	SPRING CLAMPED	1850
HYSOL 9628	250 deg	AUTOCLAVE 90 PSI	2640

SINGLE 1/2 in OVERLAP SHEAR TESTS

2 ADHERENDS ~ (±45) FABRIC

Table 20. Bonding Methods - Typical Values

BOPIDING METHOD	LAP SHEAR STRENGTH psi	
FUSION BOND	8000	
RESISTANT HEATED BOND	3800	
ELECTROMAGNETIC FUSION	3750	
EPOXY ADHESIVE	4200	
ULTRASONIC BONDING	1400	

Table 21. Attachment Studies - Hole Fabrication Evaluation

	THICKNESS (in)	CONTROL (psi)	DRILLED & REAMED (psi)	PUNCHED (psi)
4 PLY 0°/90° LAMINATE	0.022	71,000	44,300	52,000
8 PLY 0°/90° LAMINATE	0.044	70,000	64,000	62,400
12 PLY 0°/90° LAMINATE	0.066	88,000	76,000	66,000




Figure 43. Punched Hole — 1/4 Diameter (50X)




Figure 44. Drilled/Reamed Hole - 1/4 Diameter (50X)

Table 22. Attachment Studies - Reamed Hole Evaluation

HOLE CONDITION - 12 PLY (0°, 90°) TESTED IN TENSION AT + 70°F	CONTROL PUNCHED 1/4"	88,000 psi 66,000 psi
	DRILLED & REAMED	76,000 psi
	PUNCHED &	
	REAMED	77,000 psi

4.4 CHOPPED FIBER MOLDING

Present elevator fittings are machined metal designs which are quite costly to produce. Studies were therefore made to evaluate the potential of reducing these costs by producing the fittings by injection molding or close die molding using chopped fiber thermoplastic materials. Although most of the effort was expended on close die molding evaluation, some injection molding material properties were developed.

4.4.1 Injection Molding

One injection molding material was tested to establish its properties. This material was Ryton PPS made by Phillips Petroleum. Flexure specimens were cut from injection molded sheets approximately 0.17 inches thick. The specimens were oriented in both the 0° and 90° directions and were tested at room temperature and 180° F. A summary of this data is shown in Table 23.

4.4.2 Close Die Molding


A close die molded fitting design was developed which incorporated two molded pans fused back-to-back to provide the main load path for transmitting hinge loads to the elevator box assembly. Two molded trusses were also incorporated by fusion bonding to provide additional bearing area at the load pick-up point and also, additional lateral stiffness. Details of the design are shown in Figure 45.

Two types of fittings were produced. Both incorporated the two three-sided molded fabric pans fused back-to-back. One type of fitting incorporated fabric molded trusses and a second chopped fiber molded trusses.

The three-sided pan details were fabricated by first making a preform and then compacting it in an autoclave. Fabric plies were cut to the proper shape and then formed and stacked into a preform as shown in Figure 46. The preform was then placed on a tool and covered with caul plates (Figure 47). This assembly was then bagged and placed in an autoclave and the pan compacted at 200 psi and 600° F for 30 minutes. Figure 48 shows a pan after compaction. It was then trimmed to the proper configuration prior to installation in the fitting fusion tool.

Table 23. Injection Molding Material Flexural Properties — Ryton PPS (Phillips)

DIRECTION	TEMPERATURE	ULT. STRESS (PSI)	MODULUS (X 10 ⁶)
00	RT	18.2	1.8
00	180°F	16.5	1.3
90°	RT	7.6	1.1
90°	180°F	9.7	0.76








Figure 46. Molded Fitting — Preformed Fabric Pan




Figure 47. Molded Fitting — Pan Compaction Tool and Caul Plates




Figure 48. Molded Fitting — Compacted Pan Prior to Trim

Chopped graphite molding material was used to make the trusses for one of the fittings. The required amount of chopped fiber molding material was weighed and placed in a compaction tool. This assembly was placed in a press and run at 600°F for 30 minutes. Figure 49 shows a pile of the molding material and a completed truss. Figure 50 shows the truss compaction tool.

A second fitting was made using fabric molded trusses. The plies of graphite-polysulfore fabric were first cut to shape in a dinking die. They were then placed in the tool shown in Figure 50 and compacted at 600° F for 30 minutes. Figure 51 shows the dinked out plies and a completed fabric truss.

The fitting detail parts were then assembled in the molded fitting fusion assembly tool. Figure 52 shows the detail parts. Figure 53 shows them in the tool and Figure 54 after the pans have been placed in position. The fusion pool was then assembled as shown in Figure 55 and then placed in a press. Fusion was performed in the press at 600° F for 30 minutes. A completed graphite-polysulfone molded fitting is shown in Figure 56.

The first two fittings produced were not up to the desired quality. Web and flange thicknesses were not consistent. The insert tooling was changed to improve the containment of the fitting molding material by cutting back the amount of silicone used. Two more fittings were produced with the modified inserts. Their quality was much better than the original two produced.

The initial two fittings produced were tested to establish their load carrying capabilities. The fitting with the fabric molded trusses was tested for two YC-14 elevator fitting ultimate load conditions, four lifetime fatigue cycles and finally a pull-out test to failure. The first fitting (fabric truss) was bolted to a test fixture as shown in Figure 57. This fixture was then mounted in a test machine at an angle that would provide the required load components. Figure 58 shows a photo of a typical test set-up. Figure 59 shows the fitting positioning used to provide the ultimate load conditions. The fitting was loaded to two different ultimate load conditions (see Figure 59) without apparent damage. The fitting was then subjected to 120,000 fatigue load cycles at 42% of ultimate at the position #2 load condition (see Figure 59) without apparent damage. This represents four times the required




Figure 49. Molded Fitting — Chopped Graphite Fiber Molded Truss




Figure 50. Molded Fitting — Truss Compaction Tool




Figure 51. Molded Fitting — Fabric Truss




Figure 52. Molded Fitting - Detail Parts and Fusion Assembly Tool




Figure 53. Molded Fitting - Fusion Too! With Details Installed




Figure 54. Molded Fitting - Details and Pans in Tool




Figure 55. Molded Fitting - Fision Assembly Tool Ready For Press




Figure 56. Molded Fitting - Graphite/Polysulfone




Figure 57. Molded Fitting - Test Ser-Up Without Side Plate




Figure 58. Molded Fitting - Test Set-Up




Figure 59. Molder Fitting - Test Load Conditions

design life cycles of the elevator fitting. The fitting was then repositioned to position #3 as shown in Figure 59. A pull-out load was applied until failure occurred at 15,050 lb, as shown in Figure 60. The fitting failed in the web-flange radii. A close-up of the failure is shown in Figure 61.

A fitting with the chopped fiber trusses was also tested to failure. This fitting was mounted in a test machine in position #3 (Figure 59). A pull-out load was applied until failure occurred at 11,600 lb. The fitting failed in tension in the lug area. A close-up of the failure is shown in Figure 62.

Both the fabric truss fitting and chopped fiber truss fitting failed above the highest ultimate load component even though they were loaded in a more severe direction. The fitting failure modes showed that the fabric truss concept provided better load transfer capability from the lug to the bolted flange area.




Figure 60. Molded Fitting - Pull-Out Test




Figure 61. Fabric Truss Molded Fitting Failure




Figure 62. Chopped Fiber Truss Molded Fitting Failure

5.0 FIELD MAINTENANCE/REPAIR METHODS

Studies were initiated on field repair and maintenance procedures for graphite reinforced thermoplastic composites. The methods emphasized were the repair of laminate penetration or major damage under field conditions. Accordingly, facility limitations were imposed which only permitted the use of portable vacuum pressure and heat sources.

Several panels were tested that incorporated repaired areas. The panels were made of 4 plies of 181 style graphite fabric orientated at $(0^0,90^0)$ and were 6 in. wide and 16 in. long. Damaged areas 1 in., and 3 in. in diameter were repaired. The frayed area of damaged zone was removed with a hole saw of the appropriate diameter. The edges were then scarfed by making several hole saw cuts each successive one being larger in diameter and one ply deep. The end result was a stepped joint of four concentric circles as shown in Figure 63. The area around the hole was then solvent cleaned with Methanol. Individual plies of fabric prepreg were then fitted to the hole. The repair was then accomplished by adhesive or fusion bonding using a portable vacuum and heat source. A typical repaired damage is shown in Figure 63.

Several different heat sources were evaluated. They consisted of a heating blanket, localized (spot) resistance heater, hot air gun and resistance wire. Of these, the hot air gun (Figure 64) proved to be the best. The location and rate of heating was most easily controlled by this method since the operator had good visibility of the area being repaired. The other heating methods caused panel distortion due to rapid rate of heating and/or non-uniform heating.

Using a heat gun as the heat source, a patch could be heated to a temperature of 500 to 550^{0} F. It was found that a more uniform patch could be achieved if an aluminum back-up plate (x 0.060 in. thick) was used. The plate helped distribute the heat and minimize distortions. A standard fusion repair could be made in 15 to 30 minutes. Figure 63 shows a completed repair made by fusion. A cross section of a repair patch made by this method is shown in Figure 65.




Fig.;; e 63, Fusion Bond Damage Repair




Figure 65. Fusion Bond Repair Cross Section

Repairs were also made using epoxy adhesives EA934 and EA9628 (Hysol). The hole preprations were the same as used for the fusion repair. The replacement patches, however, were preconsolidated in a press (consolidated patches can also be used in the fusion process), as shown in Figure 66. EA9629 adhesive was applied between each layer of the patch. It was then vacuum bagged and then cured 90 minutes at +2500F with a heating blanket. Similar procedures were used with EA934 adhesive except the patch was cured at room temperature.

A total of 12 panels were tested. Two were used as controls. Eight repair panels were static tested. They were conducted in a 120,000 lb capacity Baldwin Universal test machine at room temperature and with a deflection rate of 0.05 in./min. Two repair panels were fatigue tested. Fatigue tests were run in a 40 kip capacity hydraulic fatigue macine with a servo load controller. The repair panel test data is summarized in Tables 24 and 25. A photo of some of the failed specimens is shown in Figure 67.

Two control panels were tested in tension, one to obtain basic panel strength and one with a 1 in. diameter hole. The first control panel was tested and initially failed in the grip area. It developed a maximum gross stress of 66,000 psi. This panel was then repaired and necked down to a 3 in. width in the test area. It failed at a lower gross stress of 50,948 psi in the necked down region in the second test. A second control panel with a 1 in. diameter hole was also tested. This panel developed a gross stress of 26,593 psi at failure.

Panels with a 1 in., 2 in., and 3 in. hole were repaired by fusion bonding. Panels with 1 in. diameter holes were also repaired by adhesive bonding. The panels with the fusion and adhesively bonded 1 in. diameter repaired holes were static tested and achieved gross strengths equivalent to that attained in the second test of the control panel. The panels with the 2 in. diameter repairs attained static strengths that were 56 percent of ultimate and panels with the 3 in. repaired holes attained strengths that were 42 percent of ultimate. The net stress of these panels based on areas after the laminates

これという社会




Table 24. Repair Panel Static Tests (a)

PANEL	AREA (IN ²)	LOAD (LB)	GROSS STRESS (PSI)	NET STRESS (PSI)
CONTRO'L NO. 1 CONTRO'L NO. 2 (1-IN HOLE, NO REPAIR) 1-IN HOLE REPAIR - FUSION 1-IN HOLE REPAIR - FUSION 2-IN HOLE REPAIR - FUSION 2-IN HOLE REPAIR - FUSION 3-IN HOLE REPAIR - FUSION 3-IN HOLE REPAIR - FUSION 1-IN HOLE REPAIR - BOND	0.1635 0.3276	8,330 ^(b) 8,830 16,540 17,100 9,260 9,600 7,420 6,720 17,250 16,220	50,948 26,593 50,438 52,197 28,266 29,304 22,649 20,512 52,655 49,511	50,948 32,343 60,585 62,636 42,399 43,956 45,298 41,024 63,186 59,413

⁽a) FOUR PLIES OF FABRIC AT (0,90)

Table 25. Repair Panel Fatigue Tests

FATIGUE SPECIMEN	GROSS AREA IN ²	MEAN + ALT. LOAD, KIPS	MAXIMUM STRESS (GROSS AREA) PSI	CYCLES TO FAILURE	NOTES
B-1	.3282	3.00 ± 2.00	15,000	7,749,000	NO FAILURE
		3.90 ± 2.60	20,000	3,823,000	NO FAILURE
		4.92 ± 3.28	25,000	2,779,000	NO FAILURE
B-1		5.91 ± 3.94	30,000	106,700	TEST FIXTURE FAILED, SPECIMEN BROKEN
B-2	.3245	5.83 ± 3.89	30,000	5,847,000	NO FAILURE

1-INCH HOLE REPAIR FUSION FOUR PLIES OF FABRIC AT (0,90)

⁽u) FIRST TEST FAILED IN GRIPS AT 66,000 PSI, MACHINED TO 3 IN WIDTH FOR SECOND TEST




Figure 67. Repair Panel Failed Specimens

had been stepped to accept the repair patches are approximately the same. They showed a significant improvement when compared to the net stress in the control panel incorporating the 1 in. diameter hole. This improvement was developed in spite of the more severe boundary conditions on the panels with the large holes by the constant 6 in. panel width.

Panels with 1 in. hole repairs were fatigue tested. The fatigue tests were run in a 40 kip capacity hydraulic fatigue machine with a servo load controller. Specimens were loaded with a sinusoidally varying load at an R = 0.2 and a frequency of 10 Hz. The first panel was tested at increasing maximum stress levels until failure occurred. The panel finally attained 2.8 x 10^6 cycles at 25,000 psi gross stress which was well beyond the safe life (4 lives) required for design. When the next load level (30,000 psi) was attempted the test fixture failed which caused the panel to break in bending. The second panel was fatigued at a maximum stress level of 30,000 psi and attained 5.8×10^6 cycles without failure.

6.0 SUBCOMPONENT EVALUATION

A subcomponent test program was performed to establish the data required to finalize the design of an AFRTP YC-14 outboard elevator. The tests in this program included static and fatigue rail shear tests, static and fatigue lap shear bond tests, mechanical attachment tests, shear buckling tests, compression buckling tests, load introduction tests and fracture panel tests. A summary of the tests performed is shown in Table 26.

6.1 IN-PLANE SHEAR TESTS

To obtain in-plane graphite composite shear data, several rail shear specimen configurations were tested (Figure 68). All of the specimens incorporated laminates consisting of Gr/Ps fabric priented at ±45° which was representative of the construction anticipated for the elevator surfaces. Standard rail shear specimens 3 in. x 6 in. were tested and developed an average ultimate shear stress of 31,000 psi. Figure 69 shows a closeup of a typical rail shear static test setup. Rail shear specimens were tested with the attachment areas reinforced, and they showed an approximately 10 percent improvement. One specimen was tested with the rails bonded in place to minimize the stress concentration due to the attachment and this one also showed some improvement. A summary of the rail shear static tests is shown in Table 27. Photos of the failed specimens are shown in Figures 70 through 72. The specimens attained strength levels sufficient to show design compliance. The failure stresses were 2 to 3 times greater than required for the YC-14 elevator design.

An additional set of rail shear specimens was tested to obtain additional strength, shear stiffness data and temperature effects. This data is also included in Table 27 (Specs 11 through 14). These specimens tested slightly higher than the initial bolted rail specimens. The specimens tested at 160°F showed no significant drop in strength and only a slight drop in shear stiffness.


Rail shear specimens incorporating the same laminate design as the static specimens were tested in fatigue. The fatigue tests were conducted in a Sonntag SF-10 fatigue test machine at a loading frequency of 30 Hz and a R(minimum load/maximum load) of 0.05. Test specimens were clamped between

Table 26. Subcomponent Tests

TEST	SPECIMEN	NO. OF TESTS
IN-PLANE SHEAR	RAIL SHEAR	17
JOINT STRENGTH		
FUSION BOND	LAP SHEAR	24
ADHESIVE BOND	LAP SHEAR	9
MECHANICAL ATTACH.	PULL OUT	13
SHEAR BUCKLING	CANTILEVER BEAM	3
COMPRESSION BUCKL'G	STIFF. COMPRESSION PANEL	3
LOAD INTRODUCTION	BOX BEAM	1
FRACTURE	SLOTTED PANEL	3

Table 27. Rail Shear Static Tests — ±45 Graphite Fabric/P1700

	i adie	27. Rail Shear Static Tests — ±45	<i>Grapnite га</i>	UNC/FI 700	
SPEC. NO.	NO. PLIES		TEST TEMP	MAX. SHEAR STRESS	SHEAR MODULUS 10 ⁶
1	4	STD. BOLTED RAILS	R.T.	30,900	
2	4	STD. BOLTED RAILS	R.T.	31,100	
3	8	DOUBLERS - BOLTED RAILS	R.T.	33,000	
4	8	DOUBLERS - BOLTED RAILS	R.T.	35,400	
5	4	BONDED RAILS	R.T.	35,600	
11	4	BOLTED RAILS	R.T.	32,520	4.0
12	4	BOLTED RAILS	R.T.	35,430	3.9
13	4	- BOLTED RAILS	160°F	31,890	3.7
14	4	BOLTED RAILS	160°F	33,430	3.5
15	4	BOLTED RAILS- 5/16" DIA. HOLE	RT.	33,400	
16	4	BOLTED RAILS-5/16" DIA HOLE	R,T	33,700	



RAIL SHEAR SPECIMEN

SPECIMEN	TEST	TEST TEMP	NO. OF TEST
NO HOLE	STATIC	R.T.	4
NO HOLE	FATIGUE	R.T.	5
HOLE	STATIC	R.T.	2
HOLE	FATIGUE	R.T.	2
NO HOLE	STATIC	160°F	3.
NO HOLE	FATIGUE	160°F	2
		TOTAL	17

Figure 68. In-Plane Shear





Figure 69. Rail Shear Static Test Set-Up







Figure 70. Failed Rail Shear Specimens






Figure 71. Failed Rail Shear Specimens — Doublers Bonded in Attachment Areas

and the state of t




Figure 72. Failed Rail Shear Specimen — Rails Bonded In-Place

rails which were attached to the test machine through spherical ball bearings such that the load time was geometrically the same as used in the static rail shear test fixtures. The upper end was connected to the fixed end of the test machine through a strain gaged load cell to monitor test loads. The lower end was connected to the test machine loading platen, which applied mean and alternating loads. An automatic control system continuously made adjustments to maintain the proper load levels throughout the test duration.

Five rail shear specimens without holes were tested in fatigue. An endurance limit was attained at a maximum cyclic fatigue stress of 16,000 psi. A summary of this data is shown in Figure 73. Two rail shear specimens with a 5/16-in. diameter hole in the center of the test section were tested in fatigue. One was cycled to a maximum stress level of 23,000 psi and failed after 71,000 cycles. This data point plotted slightly below the S-N curve is shown in Figure 73. A second specimen with a hole in the test area was cycled at a maximum stress of 16,000 psi. This specimen failed after 6 x 10^6 cycles. Typical failed static and fatigue rail shear specimens are shown in Figure 74.

6.2 JOINT TESTS

Specimens were tested to obtain fusion bond, adhesive bond, and mechanical attachment joint strength data. Lap shear specimens were tested to obtain both static and fatigue properties.

6.2.1 Bonded Joints

Several Tap shear specimens were tested to obtain properties of adhesive and fusion bonded joints. Both static and fatigue tests were performed.

The adhesive bond shear tests were performed using a 1 in. by 6 in. specimen with a 0.5 inch overlap as shown in Figure 75. Fiberglass end tabs were incorporated to facilitate gripping.




Figure 73. Rail Shear Fatigue Data




Figure 74. Rail Shear Failed Specimens

Figure 75. Lap Shear Specimen

man wednes man and the destruction of the state of the st

A series of tests was performed to obtain the shear strength of adhesives cured using different process parameters. The specimens incorporated fabric laminates oriented at $(0^0,90^0)$. Some were made using room temperature curing adhesive, Hysol EA934, that were processed with vacuum bag pressure and others processed with spring-clamped pressure. The vacuum bagged specimens had an average strength of 2,025 psi and the spring clamped specimens averaged 1,850 psi. These strengths are well above that required by design. A series of specimens were also made that were bonded with Hysol 9628 adhesive. The adhesive in these specimens was cured at 250^0 F and an autoclave pressure of 90 psi. These specimens were tested and ultimate shear strengths averaged 2,640 psi. A summary of the above test data is shown in Table 28.

Several additional lap shear specimens were tested to obtain the shear properties at temperatures covering the YC-14 elevator design temperature range. These specimens were tested at -65° F, room temperature and 180° F. They incorporated graphite fabric laminates oriented at $\pm 45^{\circ}$ to simulate the most severe load transfer condition in the final design. Specimens were bonded with AF126 adhesive cured at 250° F, with Hysol EA9628 adhesive cured at 250° F and Hysol EA934 cured at room temperature. Several specimens were also fabricated that were fusion bonded at 500° F and 100° psi. Figure 76 shows a cross-section of a typical fusion joint. All of the specimens tested attained shear strengths above that required for design.

The data obtained from the above tests showed that the AF126 adhesive produced the highest shear strengths. This adhesive is considered to be the most flexible of the group tested and therefore best able to contend with the high in-piane strains produced by the $\pm 45^{\circ}$ laminates. The Hysol EA934 adhesive cured at room temperature attained room temperature strengths averaging 1,060 µsi which is more than sufficient to meet field repair design requirements. The fusion bond specimens attained room temperature strengths of 1,210 psi and retained the highest percentage of their room temperature strength at 180° F. In general, all of the specimens tested developed strengths that would meet design requirements. A summary of this test data is shown in Table 29.

Table 28. Adhesive Lap Shear Strengths

Adhesive	Cure temperature 0 F	Pressure application	Average shear strength (psi) ^a
Hysol EA 934	R.T.	Vacuum bag	2,025
Hysol EA 934	R.T.	Spring-clamped	1,850
Hysol 9628	2500	Autoclave 90 psi	2,640 🔹

^a Single ½-in overlap shear tests Fabric (0, 90).




Figure 76. Fusion Bonded Joint

Table 29. Lap Shear Strength (psi) (4 Plies ± 45 Fabric)

Adhesive cure temperature		Te	Test temperature				
		-65 ⁰ F	R.T.	180 ^o F			
AF126	250 ^o F	2,270	2,170	920			
EA9628	250 ^o F	1,500	1,290	580			
EA934	R.T.	1,190	1,060	700			
Fusion	500 ⁰ F @ 100 psi	1,640	1,210	860			

Several lap shear specimens were fatigue tested. These specimens incorporated graphite fabric laminates oriented at $\pm 45^{\circ}$ and were assembled by fusion bonding. The specimens were fatigued in tension with a load ratio of R = 0.05. Endurance limit attained was approximately 450 psi. This is well above the limit load levels used in the thermoplastic elevator design. A summary of the fatigue data is shown in Figure 77.

The rail shear specimens were fabricated with 0.3-in. wide fusion bond along the center of their sections. Figure 78 shows the specimen cross-section. These specimens were tested and attained shear strengths of 3,220 psi and 2,990 psi which are consistent with the strengths achieved with the lap specimens. The failures occurred within the first ply of one of the specimen halves.

6.2.2 Mechanical Attachment Joints

Several mechanical attachment joint specimens were fabricated and tested. A summary of this data is shown in Figure 79. All of the specimens failed in either a shear-out of tension mode or in the specimens with doublers in the basic $\pm 45^{\circ}$ laminate. The specimens that incorporated $\pm 45^{\circ}$ laminates at the attachment (No.'s 1, 2, and 3) failed at higher loads than those with $(0^{\circ},90^{\circ})$ laminates (No.'s 4, 5, and 6). The specimens with doublers in the attachment areas failed in the basic laminates and carried the highest loads. A photo of the failed specimens is shown in Figure 80.

Nine graphite-polysulfone to aluminum lap joint specimens fastened with 1/4-in bolts were tested to determine their fatigue lives and failure modes. The nine specimens consisted of three groups of three each having different laminate construction representative of various types that had a possibility of being used in the elevator design. The first group incorporated $\pm 45^{\circ}$ laminates, the second $(0^{\circ},90^{\circ})$ laminates and the third 45° laminates with a $(0^{\circ},90^{\circ})$ doubler in the attachment area. The first two groups were attached with standard head bolts and the third with countersunk bolts. All specimens were 1.50 inches wide and had a 0.50-inch edge margin (e/d = 2).





Figure 77. Fusion Bond Lap Shear Fatigue (Fabric at ±45)





SPEC.	LAMINATE	MAXIN	NUM STRESS	(KSI)	FAILURE MODE
SPEC.	4 PLY	BEARING	SHEAR OUT	TENSILE	TANZONZ MODE
1	±45	71.8	17.9		
2	± 45	75.0	18.8		
3	±45	65.1	16.4		
4	0, 90	51.1	12.8		
5	0, 90	59.9	15.0		
6	0, 90	53.2	13.4		
7		69.1		22.8	BASIC LAMINATE
8		63.8	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	21.4	BASIC LAMINATE
9		68.9		22.9	BASIC LAMINATE




Figure 79. Mechanical Attachment Joint Test Data




Figure 80. Failed Mechanical Attachment Specimens

The tests were performed at room temperature in a Sonntag SF-1 machine at a frequency of 30 Hz. The initial load on all the specimens was equal to or greater than the load expected under service conditions. All specimens were tested at these load levels to at least 2.5 million cycles and then the load was increased to higher levels to induce for lure. The fatigue loads, number of cycles and types of failure for each for each for each in the load photo of the failed specimens is shown to give 81.

As noted in Table 30, all of the spectmens sustained 2.5 million cycles at service load levels and failed at loads significantly higher. The results obtained from the mechanical attachment fatigue tests showed that this method of load transfer can be used successfully with the types of construction to be used in the elevator design.

6.3 SHEAR PANEL BUCKLING TESTS

Three graphite-polysulfone beams were fabricated and tested to obtain shear buckling and fatigue data. The design of the shear panels in the beams was representative of the spar webs in the elevator design. Each beam used a different stiffener concept. The results obtained from all the tests showed structural capabilities that were predictable and sufficient to meet elevator design requirements.


The state of the s

The three beams were approximately 13 in. high and 24 in. long. The beam chords consisted of two angles made of 4 plies of graphite fabric oriented at $\pm 45^{\circ}$ and 16 plies at $(0^{\circ},90^{\circ})$. The webs were made of 4 plies of fabric oriented at $\pm 45^{\circ}$ and were divided into 3 bays by stiffeners. Each beam had a different stiffener design, one of which was a $(0^{\circ},90^{\circ})$ ply tee stiffener, one a $(0^{\circ},90^{\circ})$ angle stiffener and the third a $\pm 45^{\circ}$ ply angle stiffener. Figure 82 is a sketch describing the beam details.

Three shear buckling beams were fabricated. The beams were approximately 13 in. high and 24 in. long. The chords consist of two angles made of 4 plies of graphite fabric oriented at $\pm 45^{\circ}$ and 16 plies of fabric oriented at $(0^{\circ}, 90^{\circ})$. The webs were made of 4 plies of fabric oriented at $\pm 45^{\circ}$ and are divided into 3 bays by web stiffeners.

Table 30. Mechanical Attachment Fatigue Data

SPECIMEN NO.	SPECIMEN CONFIG- URATION	MAXIMUM LOAD (LBS)	MEAN LOAD + ALTERNATING (LBS)	NUMBER OF CYCLES	TYPE OF FAILURE
FJ10	4 Ply,	240	126 ± 114	7,600,000	No failure
	± 45°	480	252 ± 228	42,000	D >
FJ11		360	189 ± 171	2,661,000	No failure
		480	252 ± 228	4,996,000	No failure
		540	284 ± 256	109,000	
FJ12	4 Ply,	420	220 ± 200	2,500,000	_ No failure
	± 45°	480	252 ± 228	74,000	
FJ13	4 Ply,	240	126 ± 114	7,126,000	No failure
	0-90°	480	252 ± 228	5,136,000	No failure
		540	284 ± 256	1,292,000	3
FJ14		360	189 ± 171	2,500,000	No failure
		540	284 ± 25%	1,00G	B >
FJ15	4 Ply,	420	220 ± 000	7,719,000	No failure
	0-90°	540	284 ± 256	355,000	3 >
FJ16	4 Ply,	240	126 ± 114	2.600,000	No failure
	± 45°				
	4 Ply.	540	284 ± 256	95,000	D >
	0-90°		30, 200		
	Doubler				
FJ17		360	189 ± 171	2,500,000	No failure
, -, .		540	284 ± 256	10,000	
FJ18	4 Ply,	420	220 ± 200	10,300,000	No failure
	± 45°			. 2,222,230	
	4 Ply,	480	252 ± 228	4,700,000	No failure
	0-90°			.,. 30,000	1.55 1411416
	Doubler	540	284 ± 256	3,479,000	D >
				-,, -	






Figure 81. Mechanical Attachment Fatigue Specimen Failures




Figure 82. Shear Beam Element

general resident and the second of the secon

A Commence of the State of the

The chord angle and cap details were assembled by fusion bonding. Figure 83 shows the chord details before and after assembly. Figure 84 shows all the peam element details. Figure 85 shows a completed beam element assembly.

Static tests were conducted on all three graphite-polysulfone shear beams to determine their buckling characteristics. Load introduction and reaction plates were bolted to the test beams as shown in Figure 86. This assembly was then installed in a test frame as shown in Figure 87. The base plate was bolted to the bottom of the fixture and the load jack was attached to the load introduction plate. The loads were applied in a horizontal plane.

The center panel of each beam was instrumented with two sets of back-to-back strain gages. They were also instrumented with three deflection indicators to obtain out-of-plane deflections. A fourth deflection indicator was used to obtain load jack deflections. Figure 88 shows the location of the above instrumentation.

A Moire' displacement study was also conducted on the center bay of the test panels during loading. The stiffener side of the center bay was sprayed with a coating of flat white paint to obtain greater shadow contrast. A high frequency Moire' grid was mounted parallel to the webs and displaced from this surface 1/8 inch. The grid was supported from the panel at three points to permit it to follow the panel motion without imposing bending. The grid was illuminated with a Xenon lamp. The test setup is shown schematically in Figure 89 and a photograph of the actual setup is shown in Figure 87.

The Xenon light was directed to the panel surfaces by two mirrors which were adjusted to obtain an angle of incidence of 60° . A 100 LPI linear amplitude grid provided a sensitivity of 0.0058 in. out-of-plane displacement per fringe order. The fringe patterns produced at the load increments were photographed using a Hasselblad 500 EL camera and Kodak Tri-X film.

Each beam was loaded in 10 percent increments to an ultimate design load of 4,180 lb. The panels were unloaded and held at load increments at 60%, 40%, and zero. Moire' fringe patterns as well as strain gage and lateral deflection readings were recorded at each load increment. Figures 90 through 92 show some of the fringe patterns recorded on the panel with the tee stiffeners. Figure 90 is a typical pattern of a center panel with zero load. Figure 91





Figure 83. Chord Details- Beam Element

AND AND STANKE S



明明的时间,所以对外的时间,这个人的时候,这种时间的时间,这种时间,这种时间,这种时间,这种时间,这种时间,这种时间的时间,这种时间的时间,这种时间的时间,可以

Figure 84. Beam Element Details




Figure 85, Beam Element Assembly




Figure 86. Beam Element-Test Setup





Figure 87. Shear Beam Overall Test Set-Up



TEST SETUP DIAGRAM
SHEAR PANEL TESTS
YC-14 ELEVATOR TASK VII SUPPORT

Figure &8. Shear Panel Instrumentation




Figure 89. Shear Beam Test Schematic - Moire' Displacement




Figure 90. Shear Panel Moire' Fringe Zero Load




Figure 91. Shear Panel Moire' Fringe 50% Ultimate Load




Figure 92. Shear Panel Moire' Fringe 100% Ultimate Load

is a photograph of a typical pattern at 50% load and Figure 92 is a typical pattern at 100% load. The lateral displacement profiles were developed for each of the panels along a center panel diagonal using the Moire' fringe data. Figure 93 shows the location of the diagonal on which the lateral displacement was determined. Figure 94 shows a typical plot of the lateral displacement developed from the Moire' fringe data.

The out-of-plane deflections of the center panels in the shear beams were also obtained by electronic deflection indicators (Figure 88). A typical plot of this data obtained from the beam with the $\pm 45^{\circ}$ laminate tee stiffeners is shown in Figure 95. A buckling analysis of the beam shear web was also performed using the STAGS-C computer program. Figure 95 shows a comparison of the analytic prediction and the test data and demonstrates the excellent capability for predicting structural response of graphite thermoplastic structures.

The shear beam with the $\pm 45^{\circ}$ angle stiffeners was fatigue tested to demonstrate design safe life compliance. Figure 96 shows the load spectrum required to demonstrate a safe life of four life times. At the lower load level (118 lb/in) the center panel was at buckling coset as indicated by Figure 91 showing the Moire' fringe pattern at the approximately same load level. The beam was cycled at both required load levels for 10^6 cycles which was approximately 16 times greater than required to demonstrate safe life requirements. The center panel of the beam visually buckled at every cycle. The beam was then cycled at twice the design loads for 2 x 10^6 cycles without failure. A summary of this fatigue test is shown in Figure 96.

6.4 COMPRESSION PANEL BUCKLING TESTS

Three graphite-polysulfone compression panels were fabricated and tested to obtain compression buckling and fatigue data. Their details were representative of the YC-14 elevator cover panels. The data obtained was used to finalize the graphite-polysulfone elevator design and to demonstrate design compliance.




Figure 93. Shear Panel Schematic - Lateral Displacement Line




Figure 94. "T" Stiffener Panel Displacement Profile Zero and 100% Shear Load

Figure 95. Shear Buckling - Theory vs Test

REQUIRED

75 CYCLES AT 160 lb/in (STOL) 25 CYCLES AT 118 lb/in (CTOL)

X600 = FOUR LIFE TIMES

TEST

STATIC TEST 118 lb/in FOR 106 CYCLES 320 lb/in FOR 106 CYCLES

| 236 lb/in FOR 10⁶ CYCLES | 320 lb/in FOR 10⁶ CYCLES

Note: Onset buckling = 120 lb/in

Figure 96. Shear Buckling Fatigue Test

Care I was being the same of the state of the same of the same of

The three graphite-polysulfone compression panels tested each incorporated a different stiffener design. One consisted of $\pm 45^{\circ}$ laminate tee, one a $\pm 45^{\circ}$ fabric laminate anagle and one a $(0^{\circ},90^{\circ})$ fabric laminate angle. The compression panels were 13 in. wide and 24 in. long. Stiffeners were incorporated to stabilize the web. The stiffeners were 12 in. long thereby allowing room for the edge support along the sides of the panels. Glass epoxy pads were bonded at the ends of the panels to prevent brooming during loading. Figure 97 shows the compression panel design details.

Static load tests were conducted on all three graphite-polysulfone compression panels in a ten-kip capacity Ametek test machine. Steel channel edge constraints were used to stabilize the edges of the panels.

The center bay of the panels were instrumented with back-to-back strain gages to obtain panel buckling data and with deflection indicators to obtain out-of-plane deflections. Figure 98 shows a schematic of the compression panel test setup and the location of the panel instrumentation. In addition to the above instrumentation, Moire' fringe data was obtained to develop out-of-plane deflection data. The center bays of the compression panels were sprayed with a flat white paint coating to obtain a distinctive shadow image. A high frequency Moire' grid was mounted ilel to the webs by a three-point support. The grid was illuminated with an Xenon lamp. The light was directed to the panel surfaces by mirrors which were adjusted to obtain an incidence angle of 60°. The 100 LPI linear amplitude grid provided a sensitivity of 0.0058 in. of out-of-plane displacement per fringe with a Hasselblad 500 EL camera and Kodak Tri-X film. A photograph of the overall test setup is shown in Figure 99. Figure 100 shows a panel from the back side. In this photograph the steel channel edge constraints can be seen bolted in place and also the deflection indicators.

Each compression panel was loaded in 10 percent increments to an ultimate design load of 3,380 lb. Load, strain and deflection data was recorded at each load increment. Photos of the Moire' fringe patterns were also taken at each load increment. The three panels were loaded to ultimate load without difficulty. Onset buckling occurred at a very low load level (16 percent ultimate) as predicted by the panel analysis. A typical Moire' fringe pattern at 100 percent of ultimate load is shown in Figure 101. A typical lateral deflection plot of the center bay is shown in Figure 102.




Figure 97. Compression Buckling - Panel Elament




Figure 98. Compression Panel Instrumentation




Figure 99. Compression Panel Test Set-Up




Figure 100. Compression Panel Test-Back Side



Figure 101. Compression Panel Moire' Fringe-100% Ultimate Load

A CONTRACTOR OF STREET PRESENCE OF THE PROPERTY OF THE PROPERT




Figure 102. Compression Panel Lateral Displacement Profile - Zero and 100% Ultimate Load

The panel with the $\pm 45^{\circ}$ fabric laminate stiffeners was fatigue tested to demonstrate safe life compliance of the graphite-polysulfone elevator design. Figure 103 shows the load spectrum required to demonstrate a safe life of four life times. At the lower fatigue load level (40 percent of the ultimate) the center bay of the panel was well beyond on-set buckling. The panel therefore buckled during each of the fatigue cycles. It was successfully cycled for one million cycles at each of the load levels specified in Figure 103 which was several factors greater than required to demonstrate safe life compliance.

6.5 FRACTURE PANEL TESTS

Three slotted panels were fabricated and tested to obtain fracture data. Two of the panels incorporated four plies of $\pm 45^{\circ}$ fabric and the third, four plies of $(0^{\circ},90^{\circ})$ fabric. The panels were 6 in. wide and 16 in. long. The panels incorporated slots that consisted of a 1/2 in. diameter hole with saw cut extensions. The distance between the ends of the saw cuts was 1 in. The slotted panel details are shown in Figure 104.

namentalistis and the second of the second o

The panels were tested in tension. The panel with the $(0^{\circ},90^{\circ})$ fabric laminate failed at the same gross stress level attained with the control specimen incorporating a 1 in. diameter hole (section 3). The two panels with the $\pm 45^{\circ}$ laminates failed at gross stress levels of 15,628 psi and 17,155 psi. A summary of the fracture panel test data is shown in Table 31. A photo of the failed panels is shown in Figure 105.

The data from the panels with the $\pm 45^{\circ}$ laminates is shown plotted with equivalent graphite-epoxy panel data in Figure 106. As shown, the residual strength of the damaged graphite-polysulfone fabric panels are equivalent to the graphite-epoxy panels and well above the limit strain used in design.

6.6 LOAD INTRODUCTION TESTS

A load introduction test element was designed, fabricated, and tested. Its configuration was representative of load introduced by a fitting in the AFRTP-YC-14 elevator box design. It incorporated front and rear spars which

75 CYCLES @ 53.3% PULT


125 CYCLES @ 40% PULT

× 600 = FOUR LIFETIMES

PULT = 260 L8/IN

NOTE: ONSET BUCKLING = 42 LB/IN

Figure 103. Compression Panel Fatigue



で、語言とは、音音をは、音音をは、音音を表する。と、音音を表する。音音を表する。音音を表する。音音を表する。音音を表する。音音を表する。音音を表する。音音を表する。音音を表する。音音を表する。音音を表する。

Figure 104. Slotted Panel Test Specimen

Table 31. Fracture Panel Tests

Panel	Fabric laminate (deg)	Failure load (lb)	Gross stress (psi)
No. 1	(0-90)	8,140	24,847
No. 2	±45	5,120	15,628
No. 3	±45	5,620	17,155




Figure 105. Fracture Panel Failure and Control Panels




Figure 106, ± 45 Graphite/Epoxy Center Notched Panel Fracture Response

 $^{*}E_{X} = 2.4 \times 10^{6}$

included graphite-polysulfone webs made of fabric oriented at ±450. The spar chords were "Tees" made of fabric oriented at (0,90). The spars were connected by top and bottom covers made from 4 plies of fabric (±45). The box was 16.0 in. long and 10 in. long, 10 in. wide and 8.0 in. high. A typical rib was installed in the center of the box to distribute fitting loads. A drawing showing all the design details is shown in Figure 107. The load introduction box element was fabricated using the same detail fabrication and assembly procedures that were used in the full-scale demonstration components. The assembly was accomplished using fusion, adhesive bonding, and mechanical attachments. After the box fabrication was completed, an aluminum fitting was installed at the rib location at the center of the box.

Both static and fatigue tests were performed on the test element. The box was bolted to metal plates at its ends. The edges of the end plates were mounted at the angle required to introduce the fitting loads at the desired angle.

Two static tests were conducted in a test machine using the fixtures depicted in Figures 108 and 109. The fixtures were designed to position the box element so that a single actuator could apply the resultant of the desired load components in the forward-aft a d up-down directions. Loads were applied by a hydraulic actuator and controlled by an MTS, Model 436 servo controller. A load cell was connected between the actuator and the load link to measure applied load. Photographs of the above test set-ups are shown in Figures 110, 111, and 112. A third static side load was also applied. The test box and side plates were placed in a 10 Kip capacity Tinius Olsen test machine and a side load was applied to the fitting lug by a load rod extending through a hole in the side plate as shown in Figure 113.

Steps on a southern one of distinct building in the many of the graphing of the second

The fatigue testing was accomplished in the 90 in. machine using the same set-up as the second static test Figure (109), except that a MTS Model 430 was used to indicate the maximum and minimum peak loads.

In the first static test, an ultimate fitting load of 9,602 lb was applied. This resultant loading was equivalent to a 200-lb component into the box in the aft direction and 9,600 lb component in the down direction relative to the box. Loads were applied in 10 percent increments. The load introduction box accepted the ultimate fitting load without any difficulty.

ASSEMBLY SEQUENCE

i) DETAIL ASSEMBLY A. (2) SPARS

4, FUSON BOND SPAR CHORDS Z LS AND CAP,

E, FUSION BOND CHORDS TO NEED CEUSON BOND TO ONE SPARE

B. PR. AND LINE. COVERS

FUSION BOND END DOUBLERS TO COVER PLATES

2) ELEVATOR BOX ASSENBLY

说点:"多点是这个是不是是这是多么是是是这些的现在是是这些是是不是是这个是是这一个是是一个是是是是这种的,也不是一种的是是一种的是是是是是是是是是是是是是是是是 第一个


A. FUSCH BOND SPACE TO LOKER COVER

BINSTALL RB AND ATTACHYENT ANGLE BY FISIN BONDING

C USAL JOSE COVER USUS BLUD VECHICULA TITALIUST.

UPPER COVER-

4 PLES, 245", GOVE FARK C PER VAT L SPECIFICATION "GRANNITE FARRIC PREMPREGNATED, THERUCPLASTIC ID 80-19348-3






Figure 107. Load Introduction Test Element




Figure 108. Static Test No. 1 Setup

A STATE OF THE PARTY OF THE PAR




Figure 109, Static Test No. 2 and Fatigue Test Setup

The state of the s




Figure 110. Load Introduction Box - Test Set-Up




Figure 112. Load Introduction Box - Test Sat-Up Side View




Figure 111. Load Introduction Box — Test Set-Up, Front View

Congression Charles and Charles Charles Const.




Figure 113. Static Test No. 3, Side Load Test Setup

A STATE OF THE PROPERTY OF THE PARTY OF THE

After the successful initial static test the box was repositioned (Figure 109) and a second ultimate static loading condition was applied. Load was applied in 10 percent increments to a maximum load of 9,462 lb. This load was equivalent to components of 5,500 lb into the box in the aft direction and 7,700 lb in the up direction.

The third static test was an ultimate side load condition. A maximum load of 960 lb was successfully applied to the side of the lug fitting.

A fatigue test was performed in which 120,000 load cycles were applied with a maximum load equal to 42% of the second ultimate static load condition. This was equivalent to four life cycles at the maximum load in each ground-airground load spectrum. The load was varied sinusoidally between 3,974 lb and 200 lb at a frequency of 5 Hz. The fatigue test was successfully completed without damage to the box.

7.0 YC-14 ELEVATOR FULL-SCALE DESIGN AND FABRICATION

Three graphite thermoplastic YC-14 outboard elevator designs were developed and evaluated and one was selected for further development. The three concepts were a currugated stiffened concept, a stabilizer honeycomb concept and a "Z" stiffened concept. All of the concepts were designed using the same requirements and criteria that was for the existing flight hardware.

7.1 DESIGN REQUIREMENTS AND CRITERIA

The composite outboard elevators were designed to be a direct replacement of the existing aluminum outboard elevator on the YC-14. They were developed to utilize existing metal hinges, actuator and reaction links. The composite elevator design envelopes matched the external mold line surfaces of the aluminum design. The basic elevator structures consisted of a two-spar box similar to the aluminum design.

Design Loads

The GRTP elevators were designed for the same ultimate load conditions as the YC-14 outboard elevator aluminum design.

Ultimate Load Factor

The ultimate loads were based on an ultimate factor of safety of 1.50 applied to the limit loads.

Fitting Factors

The fitting factors used on the aluminum design were used to ensure durability and rigidity. The factors were applied to the internal limit structural loads obtained by analysis for both normal and fail-safe flight conditions.

Fail-Safe Requirements

The GRTP designs were capable of carrying limit loads with the following hinge failures occurring independently (same as aluminum design):

F/S Condition	Failed Hinge Station
1	115
2	143
3	171
4	215
5	. 265

Temperatures

The temperature range criteria for the composite designs was $-65^{\circ}F$ to $160^{\circ}F$.

Design Service Life

The design service life goal of the composite designs was the same as the C-14 (production) aluminum design:

	<u>YC-14</u>	<u>C-14</u>
Cumulative flight hours	1,000	30,000
Total number of landings	2,000	17,000
Total service life years	10	20

The composite elevators were designed to have an operational life to exceed the design service life per MIL-STD-1530 and MIL-A-8866(A). The objective of the Design Service Life requirement was to minimize potential cracking problems that could reduce the functional capability or increase the operational cost of the elevator.

Flutter

The GRTP elevators had equal or greater flutter margins than the aluminum design. In order to satisfy this criterion, the unbuckled box torsional stiffness (GJ) iistribution was equal to or higher than the aluminum desig.

Control System Effectiveness

Control system effectiveness was maintained by providing equivalent local stiffnesses in the actuator load loop structural elements.

Permanent Deformations

The composite laminate layups were configured so that no significant ply yielding would occur due to transverse and/or shear ply strains under applied limit elevator loads. For ± 450 laminates, the maximum strain in the 00 or 900 directions shall be 2,000 microstrain at limit load.

Spar_Webs

Spar webs of other than stiffened monocoque construction were designed to be buckle resistant. Intermediate elastic buckling of stiffened monocoque laminate webs was allowed. The maximum ratio of applied-to-cr ical shear buckling loads was 5.0. The strength of the critical web panel was established by nonlinear deflection analysis using a maximum ply strain failure criterion. The web strength analysis was substantiated by shear web subcomponent testing.

Cover Panels

All cover panels were designed to be buckle resistant or intermediate elastic buckle design. The cover panel strength analysis was substantiated by subcomponent testing.

Rib and Actuator Beams

All ribs and actuator beams were designed to be buckle resistant.

Design Allowables

Design data and properties for GRTP composites were determined from test data for the materials, processes, and composite configurations used in the elevator. Joint design allowables were based on element test data. Nominal ply dimensions were used for analytical calculations to substantiate structural integrity.

Damage Tolerance

The materials, design concepts and stress levels for the composite design were selected so that the probability of failure of the component is minimized due to the propagation of undetected or inservice inflicted damage. These damage tolerance requirements were achieved (1) through the use of fail-safe design in the case of a hinge failure, (2) by designing to strain levels at limit load that are below critical flaw growth levels, and (3) by requiring that damage caused by impact with small debris or hail would not reduce the strength below limit load requirements.

Corrosion

Aluminum fittings would be de-coupled from the GRTP elevator materials by two coats of corrosion resistant primer. Special consideration would be given to the fitting connection fasteners with respect to material selection and wet-primed installation.

Panel Sizing

The cover panels and spar webs were sized to provide torsional stiffness (GJ) greater than the aluminum design at reduced structural weight. For a design goal target, the GJ distribution for the YC-14 graphite-epoxy elevator shown in Figure 114 was adopted. The $\rm EI_y$ and $\rm EI_z$ distributions for the graphite-thermoplastics designs are shown in Figure 115. These distributions




Figure 114. YC-14 Outboard Elevator GJ Comparisons




Figure 115. YC-14 Outboard Elevator El Comparisons

are lower than the current aluminum design. The combined EI, GJ distribution shown for the composite design are known to provide flutter margins in excess of the design criteria requirements.

The cover panels and spar webs were also sized to ensure integrity at ultimate design loads. Classical orthotropic panel analysis methods were used to determine critical general and local instability loads. The stiffened monocoque panel concept allowed intermediate buckling as stated in the design criteria.

Fatigue and Fracture

A study of the YC-14/C-14 GRTP elevator component designs indicated they would meet service life requirements. The elevator skin and spar webs were designed to a stiffness requirement resulting in low laminate operating stresses. Limit strains for the basic skin laminates were about 2,000 in./in. due to axial and torsional loading. In order to assess the general fatigue behavior of the skin laminates, available data from the Advanced Composites Design Guide was reduced as shown in Figure 116. The reduced data does not include thermoplastic laminate data but initial studies and element tests have shown equivalent fatigue response for GRTP laminates.

As shown in the above figure all the laminates presented, including those containing holes, did not fail at maximum peak strain values below 4,000 μ in./in. The typical maximum fatigue load anticipated in each flight is expected to be only about one-half of limit load with only small load reversal resulting from take-off rotation. The maximum skin strain will be considerably below the fatigue limit. The laminates shown did not include the all $\pm 45^{\circ}$ layup used in the preliminary design but did include testing of $\pm 45/90$ laminates which would be expected to have similar performance. It is anticipated from this comparison that the basic laminates will have sufficient fatigue margin.

The preliminary GRTP design concepts with $\pm 45^{\circ}$ laminate skins surpass the requirements for in-service damage tolerance. Fracture data developed in the element tests (Section 6.0) substantiated this capability.




Figure 116. Fatigue of Intermediate Strength Graphite/Epoxy

7.2 PRELIMINARY DESIGN

Three YC-14 outboard elevator preliminary conceptual designs incorporating graphite thermoplastic materials were evaluated. The evaluation considered weight, cost, inspectability and repairability. As a result, one of the concepts was selected for further design refinement and hardware evaluation.


The laminate thicknesses and ply orientations in all three designs were selected to be as close to the existing aluminum design as practical. The YC-14 elevator is subjected to bending induced by loads from the horizontal stabilizer through the interfacing multi-hinge attachment. The induced bending loads can be minimized by reducing the elevator EI stiffness to an acceptable lower limit. In the design of the ply orientations a major consideration was the high torsional stiffness required because the elevator is actuated at the inboard end only; both the reduced bending stiffness and high torsional stiffness resulted from the use of $\pm 45^{\circ}$ plies in both the cover panels and spar webs. Figures 114 and 115 show a comparison of the bending and torsional stiffnesses between the composite designs and the existing aluminum design.

A detailed SAMECS finite element computer model has been built for internal loads analysis. A total of 16 flight maneuver and ground load cases were evaluated. Analysis results indicate the composite designs have cover panel and spar web ultimate shear load capabilities within 4 percent of the aluminum elevator loads. Torsionally, the composite design is considerably stiffer, showing 30 percent less windup than the aluminum design.


Figure 117 shows locations of hinge and actuator fittings and envelope control dimensions. These dimensions and locations were maintained throughout the program to assure interchangeability of GRTP and aluminum elevators.


7.2.1 "Z" Stiffened Panel Concept

A graphite-polysulfone YC-14 elevator design was developed incorporating a panel concept with chordwise stiffeners. The details of this design are shown in Figure 118. The covers and spar webs used graphite fabric oriented at ±45° to provide good torsional stiffness. Panel stability was provided by



THE PROPERTY OF STREET OF STREET STRE





GEAMINE FARK - HEIGH THOO SI STILE / PLITSIL FORE GEAPHITE TAPE HEIGHES AS / PLITSIL FORE

- E BOTTOM COVERS

 1) SAIN, CONSCIDATION HOT BOLLING, ATOCIANE OR MATELSION

 2) TRIM

 3) L' SECTIONS ("SAIN ST FFEMETS & ROS (MICRO)" PITTUSIONS

 4) ANGLE SECTIONS ("SAIN CHOPOS & STIFFEMER ATTRICHMENTS) PULTE JUICAS

 3 ASSENBLE SLAND, L' SECTIONS & ANGLE SETTORS BY RISON

I MED CHANNET CONSCILDATION FOR STOP I) ABOVE IT THE MEDIT OF THE MEDI

) TOP 8 BOTTOM CORES RIMS AND FRONT SOME ASSEMBLED BY FUSION O REAR SPAR AND HANGE FOTINGS INSMILED MITH MECHANICAL ATT.

NOTE: THIS DESIGN WILL BE UPDATED AS MANUFACTURING DEVELOPMENT AND FEASIBLITY STUDY RESULTS ARE OBTAINED

SEE WITH PROPERTY OF STREET	CONC GUAL	CONT CAST NAMED IN	THE MOEIN'S COMP MY
DIRECTORING AND IN MICHES	TIMAT	-	
TOLERANCES ANGLES	BATE & PRICE	<u>مم</u>	VC-14 ELEVATOR GRAPHITE/ POLYSULFONE
BECOMES AND		TIS ST TANDARS CAPE	
STATE SECT SOOF MARCHY . FR.		MGKT AMROVAL	Z' ST FFENED COVER CONCERT
THE STAL COMMENTAL STAN	Created ville to talk ?	Indiki amova	81205 SKII-81477
MT IN THE COMME CAME	CHANGE ATEM MARKET		IRICOZIDIZI OLITI
	<u> </u>	L	EAR WITH P
*****	pers ones		

171 Figure 118. YC-14 Elevator Gr/Ps Z Stiffened Cover Concept


stiffeners installed by fusion bonding. Ribs, which also use graphite fabric oriented at $\pm 45^{\circ}$ were installed at each of the hinge locations. Some flanges on both the ribs and spars were post-formed as an integral part of these details. In most cases additional angle details were added by fusion bonding to provide a means for controlling assembly tolerances. Fusion bonding was used wherever practical for detail installation and component assembly. Mechanical fastening was held to a minimum and used primarily for close-out of the elevator box.


7.2.2 <u>Corrugated Stiffened Panel Concept</u>

The design shown in Figure 119 utilized a corrugated stiffened panel concept. The top and bottom covers, and the front and rear spar webs were designed with graphite fabric oriented at $\pm 45^{\circ}$ to provide good torsional stiffness. These laminates were then stiffened with corrugated panels made of graphite fabric. The corrugated panels were fusion bonded to the flat lamination. Ribs, which were also made of graphite fabric oriented at $\pm 45^{\circ}$ were installed at each of the hinge locations. The flanges on both the ribs and the spars were post formed and were made as an integral part of the spar and cap details. The overall elevator was assembled by mechanical attachments.

7.2.3 Honeycomb Stiffened Cover Panel Concept

A design was developed that incorporated a honeycomb stiffened cover panel concept. This design was based on a 8 ft long graphite-epoxy YC-14 elevator component that had been fabricated and tested. The component tests demonstrated complete design compliance. This component demonstrated a safe life capability (4 factors) in which two of the life cycles were performed with 2 in. long saw cuts in both the covers and spar webs. After the fatigue cycling was completed the component was tested to failure. Failure occurred at 60 percent above design ultimate. Figure 120 shows the portion of the elevator that was used for the graphite-epoxy elevator test component and the structural concept that was incorporated. Because of the excellent performance








Figure 120. Graphite/Epoxy Elevator Test Component

Particles of the contract of the companies of the contract of


of this component, a graphite-thermoplastic design was developed based on the same concept. Figure 121 shows the details of this design. The top and bottom covers have graphite fabric polysulfone skins stabilized with Nomex honeycomb. The spars and ribs utilize graphite fabric/polysulfone laminates oriented at $\pm 45^{\circ}$. Stiffening is not required for these elements. The rear spar and the covers were assembled by fusion bonding. The front spar and hinge fittings were installed with mechanical attachments.


7.2.4 Preliminary Design Study Results


Three preliminary designs of a graphite thermoplastic YC-14 elevator were developed as described above. The three concepts were evaluated and the stiffener stabilized panel concept was selected for further evaluation.

Weights of the three designs were established. It was determined that all three concepts weighed within a few percentage points of each other. This study also showed that all three composite designs were approximately 25 percent lighter than the existing YC-14 aluminum elevator design.

A study was also performed to determine the costs for producing the three composite designs. Costs were based on the procedures described in Section 3.0. Costs were determined for the first unit production and then using an 85 percent learning curve for the 10th and 100th unit production. A summary of this data is shown in Table 32. These results show that for the first unit production the honeycomb design is the least costly, the "Z" stiffened next, and the currugated design most costly. By the 10th unit production the honeycomb concept remains the least costly, the positions of the following two were reversed. The "Z" stiffened concept has the highest cost because it has the greatest number of details. These costs could have been reduced by simplifying the stiffener geometry and by using integral rib flanges to reduce the number of parts. Using these techniques, most of the 10 percent cost difference (10 unit) could be elminated. The Z-stiffened is more applicable to other aircraft components than the other two concepts thereby permitting wider dissemination of the technology developed in this program. The data generated in this study indicated that all three concepts could be fabricated for approximately 25 percent less cost than the existing aluminum design.







NOTE: THE DESIGN NEW BE UPDEED & MANAGEMENT OF VELOPMENT AND FEATIBLE ? STUDY RESILED ARE OBTIQUED.

	7					
		5.0464	-111	77-14 ELEVA 6x45-1176/PD	702 45.49.4	
		7300C		HE STATELLE	2 00 52 CX	.=-
::				=		

Figure 121. Honeycomb Stiffened Design Concept

Table 32. Cost Summary -- Graphite/Polysulfone YC-14 Elevator

	UNIT	PRODUCTION HOURS	MATERIAL DOLLARS	TOOLING HOURS	TOTAL COST DOLLARS
HONEYCOMB	1	1,087	1,654	2,075	96,520
	10	7,735	16,540	2,075	310,840
	100	47,560	165,400	2,075	1,654,470
CORRUGATED	1	1,185	1,600	2,870	123,250
	10	8,432	16,000	2,870	355,075
	100	51,848	160,000	2,870	1,801,555
"Z" STIFFENED	1	1,468	1,650	2,106	108,870
	10	10,446	16,500	2,106	393,060
	100	64,230	165,000	2,106	2,155,080

Additional areas that were considered and evaluated prior to selecting a concept for further evaluation were inspectability and repairability. The stiffener stabilized panel concept scored highest in these areas. Both the honeycomb and corrugated designs incorporate areas that have restricted accessibility and were therefore more difficult to inspect. The stiffener concept resembles present metal construction and therefore would more likely lend itself to established repair procedures.

As a result of the preliminary design study, the stiffener stabilized panel concept was selected for further design refinement and hardware evaluation. The manufacturing techniques required for producing this concept were applicable to the other two. Techniques and processes in areas of consolidation, post-forming, bonding, and machanical assembly would be applicable for all three. This concept was not the most cost effective of the concepts studied but it still represented a significant cost saving when compared to the existing aluminum design. This design has greater accessibility and therefore is easier to inspect. The configuration of the stiffener stabilized panel concept closely resembles commonly used metal designs and therefore its development would be more applicable to aircraft design.

7.3 DETAL DESIGN AND ANALYSIS

は、一般のでは、1980年には、1980

A final design of a graphite-polysulfone YC-14 outboard elevator was prepared. It was based on a stiffener stabilized concept as a result of the conclusions reached in the preliminary design studies. The elevator component was designed to be a direct replacement for the existing YC-14 aluminum elevator. Design drawings were sufficiently detailed to supply all the manufacturing information required to fabricate the elevator component.

The composite design was analyzed to show that all design requirements were met. A finite element model of the elevator was prepared. A Structural Analysis Method for Evaluation of Complex Structures (SAMECS) computer program utilized this model to establish the structural stiffnesses and internal loads. These loads were used for performing detail stress analysis.

7.3.1 Design

The Gr/Ps YC-14 elevator was designed to be a direct replacement for the existing aluminum design. Its reaction link, actuator and rib hinge fitting stations were the same. It incorporated two splices at locations shown in Figure 122 to accommodate available facilities. It had the same envelope, spar and cover locations as the existing design. The composite design also provided the same clearances and offsets required to permit the installation of the adjacent fairings (Figure 123). Its torsional and bending stiffnesses closely matched existing aluminum design.

Design drawings were prepared in sufficient detail to supply the manufacturing information required to build the composite elevator. These drawings are shown in Figure 124 through 129.

A design study was made of the different thermal growth between the composite elevator and adjacent structures and the associated adjustments required in design. It was determined that for the maximum spread in design temperatures (-65° to 160°F) the differential growth between the composite elevator and interfacing aluminum structure would be 0.72 in. Two fitting designs had been developed on other programs which permitted the required differential movements. These fittings had been mocked-up as part of their evaluation and both were found functionally acceptable. The design selected for the AFRTP elevator is shown in Figure 130.

7.3.2 Analysis

A "SAMECS" finite element model of the YC-14 graphite-polysulfone elevator box was developed and used to determine deflections and internal loads for use in designing the box. Figure 131 shows a plot of the model, which contains 565 nodes, 623 plates, 634 beams, and 32 load cases. Every rib and stiffener in the elevator box had been included in the finite-element model. The load cases considered include air pressure loads, actuator loads and imposed deflections at hinge points due to stabilizer deflection. The internal loads developed from the "SAMECS" analysis were used to check the buckling strength of the upper and lower surface skins and the spar webs using the "STAGS-C" finite-difference buckling analysis program. The finite-element model was also used in determining the ability of the design to attain ultimate load conditions.





Figure 122. Elevator Splice Locations



,我们是一个人,我们是一个人,我们是一个人,我们是一个人,我们是一个人,我们是一个人,我们是一个人,我们是一个人,我们是一个人,我们是一个人,我们是一个人,我们

Figure 123. YC-14 Elevator Fairings

ON PORTING AND PROPERTY OF THE PROPERTY OF THE POST OF

THE REST PART FAST THE PER SHOW THE 11 12 081 INGE FIG STA 1'S OD CZ Z 246-183216-1 A2-2 748-1832%-1 NO FTS 19395 SUPT FTG 7442-163217-1 SUPT FTG . A3-2 748-485217-3 RCTN FTG STA 122.38 (3-2 748-183220-1 ACTR FTG STA :23 37 13-2 746-183220-17 748-183720-5 RCTN FTG STA 134.34 C3-2 4 to 1 1 124 I MAGE FTG STA 143 00 C4-2 746-163219-7 748-183ZZD-9 ACTR FTG STA .57 33 C4-2 1 PCTH FTG STA 44 32 45-2 748-183220-13 748-16328-7 MINGE FTG STA 171.00 CS-7. 748-183216-1 WS FTG SAPT FTG 748-1837-7-5 13.5 July 146 33.4 85-2 748-183217-7 SUPT FTG MAGE FTL STA 25 00 C7-Z 148-153215-13 TAS FTG 149-18326-3 SUPT FTG CHAIN TON SUPT FTE 748-183217-11 MINGE FTG STA 265 00 C3-2 748-1832/8-19 69 2 TAR ETG 748-183246-1 **89**-2 146-183217-13 भूग गढ SUPT FTG 89 2 748-1832A-5 HALE FTG STA 305 00 CI-2 748-18325-1 81-2 TNB FTG 748-163214-19 01-2 SUPT FITS **(2)** ACT BEAM ANGLE - 236 -235 DOUBLE cr-- 234 DOUBLER ku-C12-4 MALLE - 233 8 1 - 232 UP J11-4 Cir. -231 WEB L ANLLE 51A 164 32 AIQ-3 - 230 229 MYLE STA 50 34 A8-3 STA 143 20 A11-3 - 224 ANCLE 227 WLE STA 136 36 ARES 7 STA 22 38 AS-3 - 226 MICLE DOUBLER STA 3/6 95 A1-3 -225 224 441LE A1-3 ANGLE 223 MILLE -222 Sec. 165 364 452 AL 3 221 MILLE A2 3 ANGLE - 220 - 219 NCLE A2-3 STA 305.00 A11-3 - 218 MUBLER AND THE PROPERTY OF THE PROPERTY OF THE PARTY OF THE PART - 217 NUE 11 12

			,	-	Special Control	eringer.	40 ,	,	soriera B	S Paragraph .		· Sealest	
		-			-	-							
													учкужелогае
<u>2</u> 2 file			9					8					7 3
塞 1	216	MILE STA . 5 COLI 3	(II)					لليا	1	154	ANGLE 24 40 30	62.5	3
E 1	۵۶	MILLE . 4 AR 3								153	SEUSLER HA 237 40	o 3	1
i i	- 2,4	ANULE AIZ 3	,		<u> </u>				2	-152	ANGE ,	3, 3	Ĭ.
€ 1	V3	MICE LIZZI	J.		\sqcup \vdash	╎ ᆛᆛ		_ _ _	4	٤١	ANGLE .	613	
	- บเ	MILE . LES			\sqcup	\vdash	4-1-1	_ - -	· ,	-150		1.2 6	
	<u>۲</u> ۱۱ ک	2008LER STA 297 35 AT 3			╂┨╶┝╴	┞╌╂╌╏	┦╌┼	+		140	ANGE	31.4	
ğ 2	200	A 166 A 3	и		╁┤╶┝╌	┠╼╂╼╂		╌┼╌┤	- i	148	ANGLE	62.3	
2 2	ZON	ANGLE . AI 3			H \vdash	├ ┼┼	+	╼╂╾╂╾╁	 	146	CENTRALE STA ZET SE		⊢
문 문 보	207	ANGLE A , ALS			H	 	$\dashv \dashv \dashv$	╼┾╶┼╾╽	1	-145	ANGLE	13	
§ .	26-	ANGE ALS			77 -	- -			-	144	MIGLE .	9, 5	3
<u> </u>	205	MILE AZ3							1	-143	MGLE	23	ing had been been been been been been been bee
82 1	VA.	ANULE . 11 AZ 3	•							142	MGE .	63	
ž /	203	UNIXIR 'JA 285 L5 3-3		\bot	\Box	Ш	$\perp \Box$		\bot	-141	NIGE	8/2	2,445
2	202	NIGLE . US		_	 	┝╌┞╌	441		<u> </u>	- 140	MILE	62 3	- 2
2 2 1	- 200	MICLE , BIS		- 	+-	┝┵┤				135	CLUBILE STA 215 00	↓—	
	- 139	MIGLE , , (93		- - 	╁┨ ┝╸	┞╌╁╌┤	- - - 	- - -		-136	MUE	A4 3	<u></u>
	95	ANGLE B13			╁┤╶┟╴	╁╌╁╾┤	╁┼┤	+++	-i	137	Arace	A 3	
9 1	197	MIGLE . 1075			╁┨╶┟╌	╁┼┼┤	╅	╼┼╾┼╾┤	+	155	ANDIER	A- 5	
ş , l	176	DOUGLER STA 2HI 95 BI 3			 	- -	+++		+-	-134	MGE .	M 3	i j
2	155	MIGLE . 01-3			<u> </u>	- -	+++		-	- 133	ANGLE	A4 3	
\$ 1.2	194	MGE 84 5			T	 	111	_ - -	1	- 137	ns	A5 3	
Ę ı	193	HULE . D. S							1	13.	SCOULER STA 205 DG	81 3	
	172	MAGLE 151 5			\sqcup	Ш	$\Box\Box$		2	- 136	AHGLE .	813	PA 454 152 153 153 153 153 153 153 153 153 153 153
	191	ANGLE . 02-3			41 C	Щ	$\perp \Box$	$\Box\Box$	2	152	MICLE .	34 5	**
on .	1%	MILLER STA 274 20 3:-3	•		 	\square			•	-128		31-3	
2	- 145 148	MVAF 2 913			╎ ┤ ├-	$\mid \rightarrow \mid \rightarrow \mid$	444		! 	-127	MIGHE	64.3	
2 2 2	187	MV.LE		+ + + -	┼┤ ┝╴	$\vdash \vdash \vdash \vdash$	+++	- - - 	+-	- 126	MIGLE -	32-3	
	186	ANGLE BIS		 	H \vdash	┝┼┤	- - - 		. - 	- 125	MIGLE STA 19) GG	-	7
	185	ANGLE . BIS		 	 	HH	+++	-+-	2	-143	MIGLE . "	B1 3	~ 養
E	1654	ANGLE (923)		 - - - 	Ħ₅ H	$\vdash \vdash \vdash \vdash$	+++		2	- 122	AMGLE	813	
A 1	163	MULG R73				<u> </u>	 	_ - - -	1	121	MIGLE .	G- 3	
	167	COUGLER STA 245 (7) Au 3	· ·		II [- l'th	MGE , .	6-3	
g i	181	ANGLE A63			H Γ	Ш	$\bot \Box$	$\Box\Box$	<u>- </u>	119	ANGLE	62 3	
		Attrace is a April		++-	44 F	$\sqcup \sqcup$	$+\!$	+	<u>- </u>	118	ANGE	62-2	
12 1 E	118	DUFFER + 4 M-3			$H \vdash$	┞┼┼┤	+++		-	- 117	DOUBLEY STRIBBUS	+	
	111	MICLE + - M3		+++	$H \vdash$	┞╌┼╌┤	╼╂╼╂╾┦		<u>-</u>	- 115	ANGLE	313 B13	2.0
1	76	MIGLE W " AS 3		- - 	H	┞╌┼╌┤	╌╂╌╂╼╂	╼╂╾╂	-	- 114	ANGLE	643	
31	175	P-6 . A5 3	4	- - 	┧	┝┼┤	 - - 		-	~ 113	MGLE . "	8-3	3
ş ı	17,4	GARLER 3A 255 70 31-3		- - -	Ħ . ⊢	\vdash		+	-1-	- 112	MIGLE	69 3	1
5 2 2 2	173	NATE 1 01-3					111	_ - - -		- 111	MOLE	62.3	
2	IJζ	ANCAE - 0 0-3	•						•	~ 110	DOUBLER STA 181 GS	EU 3	
*	ווי	MILLE			\sqcup	Ш	\Box		2	- 105	MUE .	os 3	3
§ !	170	MVAE , ,, (913	- "		H	Ш			4	- 109	ANGLE	U 3	- 4
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	167	MUE			H \vdash	┞╌╁╼┤		╼┼╌┼╌┤	4_	- 107	ANGLE	B) 3	
1 2	16.7	DIEMBLER STA 248 (D E) 3		 	H \vdash	┞╌┼╌┤			┼-	- 105	ANGLE	67.5	
2	144	ANIAE , , 813	,	- - 	H	┝┼┤	╌┼╌┼╶┤	- - - 	: -	- 104	ARGLE .	62 3	
第21	165	MVAE , BJ3			 	- -	╅╅	╼╂═╂═╂	+-	- 103	CLUBLER SIA OI DO	—-	7.8
§ 1	154	MILE " " (9 3		1 1	†		+++		- -	- 102	AHELE .	A4-3	3
§ /]	43	MGE 03								-101	ANGLE	4+3	3
1	• 4-5	ANIAE CAS			Ц Г				1	-100	PIB	No.5	732
	161	MICLE . , 192-3		4-4-	H	Ш	$\Box\Box$			- 33	ANGLE	M-3	
ž 1	160	COURLER STA AO TO D 3		- -	$H \vdash$	$\sqcup \sqcup$	444		┷-	96	MGLE , ,	M3	
2 2	- ISB	ANGLE . 8-3			∔{	$\sqcup \sqcup$	_}_}			-57	MGLE ,	M3	
2 1	- 158	ANGLE . BIS			╂┤┝	├ ─┼─┤	╌┼╌┼╌	╌╁╌╁╾┥	∸}	-35	RIB 4 -	A5-3	
2 1	-156	MIGLE , 93	- "		+1 -	┞╌╂╼╂	┵┵		- i	-35	DOUBLER STANKA SI	1~3	<u> </u>
<u> </u>	-155	ANGLE EU3		 - 	ᆏ┝	┝╌┼╾┼	╌╁╌┼╌┤	╌╂╌╂╼┨		93		1	
A Transfer	Augri da Augri-rang Maggan	**************************************				<u> </u>		== == ===		AND SECTION	especialists or partiety for		SETTEMA APE PERSON
होता <u></u>	<u> </u>	Pivit	\$ Left										Arts Uet
lean tex			1.00	6561 1	1								
<u>K.</u>				De De I	 				,				
Ē		ı	•		1			8			L L		4.79

A TOP		-				Serior dist				
		and the second of the second of	a en la um eigenen		20 W. 40 Z	Te Siu				
	TS	e esterijenim				•	- -	* ,	-	قلــ ق
										5
			7				6		r	5 3
	154	ANGLE STA 240 30 82 3	<u>(</u>		1		Ž		ANGLE STA HA 32 AG 3	(2)
		DOUGLER STA 232 40 61-3			7				-NGLE A03	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		ANGLE							ANGLE AO 3	
		ANGLE BIZ	4		\blacksquare		4444	-98 -87	ANGLE . ADJ	, s
		MILE . 192-3		 - 	\pm			-%	26/3_FK STA 1.33 31-3	
	+	ANGLE . 11 82-3	-		$\overline{}$			-85	ANGLE . 01-3	• 3
		ANGLE L - 0-3	· · · · · · · · · · · · · · · · · · ·					- 82	MGLE 813	. 2
	-144 -11 ,-	MICLE . 913		 	-H	 	- 	- 82 - 81	ANGLE 523	• ±
e di		MCLE , - 03	•						200 BLER 5TA 20 34 46-3	
è		MGLE 523			-H		++++	- 79	 	ve eve
	-139	DUBLER STA 215 OC AL3			山		2		ANGLE - 483	· · · · · · · · · · · · · · · · · · ·
		MGLE 443		 	\dashv	1-1-1-1-1		- 75	MIGLE . AS 3	्रं (व)
	-134	RiB ALS	N				 		ANGLE . AZ 5	• 33
	-135 -134	NOBLE		 - 		 	++++	- 72	RIB	
	- 133	ANGLE . 4 A4-3	•		#		 	71	TXURLER STA M3 60 AIT-3	
- E	-132 -131	POUBLER STA 205.00 81-3	•	 		 	2	- 70	ANGLE . ALT	
		ANGLE . JI-3	•					- 48	ANGLE . MUST	
	- 12'9	ANGLE	*	 			╫┼	- 67	ANGLE AR 3	<u> </u>
	-127	MGE . > 31-3						- 65	RIB - ARZ	
E .	-124	MGLE 31-3	4	 		 	- 	- 63	100000	
	- 124	DUBLER STA 197 00 843						- 42	ANGLE STAIGHT AND	69 67 26
	- 123	MCLE 81-3	•	 - - 				- 40	MALE AV3	12
	- 121	ANGLE 013	•					· 59	ANGLE . AO3	
	- 120 - 119	MGLE . 61-3		╂╼┼╼┼┼		 		- 57	ANGLE . AOJ	
	- 118	ANGLE . " EC-3					,	54 -55	RIB 40-	
		MIGLE 313		+		++++	1 2	-54	ANGLE 1 / CI3	
		ANGLE BI 3		 				- 52	ANGLE - 33	46
	- 113	MGLE 813		 	-H			- 51	ANGLE 82-3	
	- 112	MGLE , 62-3	 		————		 	- 50	ANGLE 32-3	
	- 110	POUBLER STA IBI OS 81-3						-48		
	- 109	MGLE 01-3			口		2	- 47	MISLE STA 122 38 A8-3	
	- 107	ANGLE G-3		1!!				- 45	ANUE - 1 483	
24 ·	-106	ANGLE 873	 	 		++++	1 1	43	ANGLE . AB-3	<u></u>
	- 104	ANGLE . FR-3			二廿			42	ANGE 483	
	- 103	DOUBLER STA 171 00 Ap3	}			} 	┞╏ ┩┪	-41	00081EP 57 15 00 40 3	\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	-101	ANGLE A43		 				39	ANGLE 4-3	
	-100	RIB . 1 Mr3				 		-39	RIB A43	Ž.
	- 78	NIGLE , . M3	•		二日			-34	MINE - MI	
145	-37	MGLE _ , M3	. 	╅╾┼╾┼┼	-+i	<u> </u>		34	ANGLE . M-3	a a
.x1)	-95	DOUBLER STAILA.32 A9-3	•		二月	HHH		-33	KIB 453	
	-93	<u> </u>		<u> </u>			 - - - - - 	-3-	Nett 33	Ž.
	FIGHT OF CAMPAGE	reference any reservoir and design of the second se	MATTER LIST					OFFI SHOWING CARREST	special visual de describiration (Sept.	SATEMAN AND SPECKETON
										II.
<u>.</u>			7				6			5
X										
医尼										
*	Transfer of the Control of the Contr					<u></u>				







Figure 124. GRTP Outboard Elevator YC-14 (Sh 1)


THE VALUE OF THE PROPERTY OF THE STATES OF T


は 大きな できる できる できる かんと






































The second secon


Over the same of







A MANAGEMENT OF THE PROPERTY O



$$\triangle T = -65^{\circ} - 160^{\circ} = 225^{\circ} F$$
 $\triangle \alpha = 13 \times 10^{-6} - 1 \times 10^{-6}$
 $= 12 \times 10^{-6} \text{ in/in/}^{\circ} F$
DIFFERENTIAL GROWTH $= \triangle T \times \triangle_{\alpha} \times L$
 $= 225 \times 12 \times 10^{-6} \times 228.45$
 $= 0.62^{\circ}$

Figure 130. Differentia! Thermal Growth




Figure 131. YC-14 GR/PS Elevator SAMECS Plot

8.0 FULL-SCALE ELEVATOR TOOLING AND FABRICATION

Three full-scale GRTP YC-14 elevators were fabricated. They were assembled in three sections to accommodate available facilities and present technology. The assembly splice locations are shown in Figure 122. The materials were initially compacted, cut and formed into details and then assembled into subassemblies. These were built into the three major assemblies as summarized in Figure 132. These were then spliced together to form the completed elevators.

8.1 ELEVATOR DETAIL FABRICATION


Front and rear spar stiffeners were molded using match die tooling. A four-ply pre-mold material was placed in a die which was then put in a press. This assembly was heated to 650°F and held at 200 psi for 15 minutes. The dies were than removed from the hot press and placed in a cold press until parts cooled below 250°F. Figure 133 shows molded stiffener details on the left and pre-mold layup in the die on the right.

Rib details were also molded using match die tooling. The male tool was machined from plate and the die cover was formed in a hydropress. Figure 134 shows the rib tooling and a completed rib. The rib materials, four plies of fabric at ± 450 ; was pre-formed in a press at 600° F and 200 psi. The pre-compacted ribs were then bagged and heated in an autoclave to 600° F for 30 minutes at 200 psi to complete their fabrication.

SOFT STREET STRE

8.2 SUBASSEMBLY FABRICATION

The lower chords and skins were assembled by fusion bonding and the balance of the elevator subassemblies were assembled by adhesive bonding. The adhesive used was Hysol 9628 which was cured in an autoclave at 250°F and 50 psi. Figure 135 shows some of the rib and chord details and two of the lower skin subassemblies prior to being trimmed. Figure 136 shows some of the front and rear spar webs with their stiffeness bonded in place.



ARROWALD PROPERTY.




Figure 132. Thermoplastic Elevator Assembly Sequence

Figure 133 Stiftener Match Die Fooling and Details

arendaren erenga sebendaran anber anber per berengan berengan berengan keringan keringan keringan berengan ber

TO AND AND ASSESSED OF STREET, STREET,

Figure 134. Matched Die Rib Tooling and Completed Rib





Figure 135. YC-14 Elevator Subassemblies



A CONTRACTOR OF THE PROPERTY O

Figure 136. YC-14 Elevator Spar Web Assemblies

A fusion tool was designed to assemble the spar chords and doublers to the bottom covers by fusion bonding. This tool was made to assemble the three different size cover sections along the length of the elevator. This was accomplished by relocating one set of chord pressure bars as required to produce the various size panels.

The bottom fusion panel assemblies were made using precompacted materials and "Tee" details that were either made of pre-formed material or pre-compacted sections. The skin and doublers were cut from autoclave pre-compacted sheet stock. The initial panels used pre-formed "Tees" that were compacted during the fusion assembly cycle. The later panels incorporated pre-compacted "Tees" during assembly which produced improved components.

Prior to the fusion assembly cycle, the tools and parts were cleaned. The details were then placed in the fusion assembly tool. Figure 137 shows the details in the tool prior to the installation of the chord pressure bars. Figure 138 shows the fusion tool with the chord pressure bars in place. This assembly was then bagged, as shown in Figure 139, placed in an autoclave and processed through a fusion cycle of 30 minutes at 6000F and 200 psi. The assembly was then cooled and the assembly removed form the tool. Figure 140 shows a completed bottom panel fusion assembly.

8.3 ELEVATOR ASSEMBLY TOOLING AND FABRICATION

Two tools were fabricated to assemble the elevator sections. One tool was used for the more complex large section and the second tool was first used for the assembly of the middle section and ther readjusted to hold the details for the assembly of the smaller end section of the elevator. These tools were primarily used to locate the details and provide pressure during the adhesive bonding. Figure 141 and 142 show two views of the large section tooling. Figure 143 shows a view of the middle and small section assembly. The lower cover assembly was initially located in the tool. The ribs were then locked in their proper locations after placing film adhesive at the bond interfaces (Figure 144). Rubber pads backed with metal bars were then used to distribute the bonding pressure provided by torqued set screws. This assembly was then placed in an oven and processed through the adhesive 250°F cure cycle.

The first of the second of the



Figure 137. Details Located in Fusion Assembly Tool



Figure 138. Details in Fusion Tool With Chord Pressure Bars in Place

TO SHEWED TO SERVED SER




Figure 139. Fusion Tool, Loaded, Bagged and Ready for Fusion Cycle




Figure 140. Completed Side Panel Fusion Assembly - 80 Inch Length




Figure 141. YC-14 Elevator Large Section Assembly Fixture - Front View




Figure 142. YC-14 Elevator Large Section Assembly Fixture — Side View




Figure 143. YC-14 Elevator Middle and Small Section Assembly Fixture





Figure 144. Details Placed in Assembly Fixture






Figure 146. YC-14 Elevator Section Assembly

The spar webs were installed using pressure plates and reaction frames (Figure 145). Upper chords were then placed in their locations with adhesive (Hysol 9628) and held in place with "C" clamps and pressure bars. These assemblies were then placed in an oven and processed through the 250°F adhesive cure. Figure 146 shows a typical elevator section subassembly after the ribs and spar webs and chords have been bonded. The three elevator sub-sections were then assembled with mechanical attachments and Hysol 934 room temperature curing adhesive as shown in Figure 147a. The elevator covers were then installed with mechanical attachments or a room temperature curing adhesive (EA 934). The first two test elevators assembled used Visu-Lok blind fasteners for installing covers in the two smaller sections and nut plates and bolts in the larger sections. Figure 148 shows a cross-section through a typical blind fastener installation. The covers on the third elevator assembly were all installed with nut plates. Figure 147b shows a completed graphite thermoplastic YC-14 elevator assembly.





Figure 147a. YC-14 Elevator Assembly-No Covers



CONTRACTOR OF THE PARTY OF THE

Figure 147b. YC- 4 Elevator No. 2

AND PROPERTY OF THE PROPERTY O




Figure 148. YC-14 Typical Viso-Lok Blind Fastener Installation

9.0 DEMONSTRATION ARTICLE TESTING

Static and fatigue load testing were completed on three graphite/thermoplastic YC-14 elevator boxes.

The first two elevator boxes were fabricated per drawing 180-56561. Following fabrication, the boxes were instrumented with strain gages as indicated in Figures 149 and 150. Rosettes #7 and #8 were not installed as originally intended because of interference with cover reinforcements. On Box #2, the interior gages were omitted because some of the cover fasteners were cemented in and could not be removed at the time of strain gage installation. The elevator boxes were also instrumented with electronic deflection indicators (EDI), and load cells to measure loads applied at 4 load points as illustrated in Figure 151.

The elevator boxes were tested in fixtures fabricated and assembled per drawing SK2-5611-0-243, and illustrated in Figure 152. Loads were applied by servo controlled hydraulic actuators at 4 loading points as noted, and reacted at two lug fittings at the outboard end and one at the centroid of the inboard end. All loading and reaction points were equipped with self aligning spherical ball bushings to allow for twisting and bending of the test article. Test loads were programmed and the hydraulic actuators controlled by the ELCADS system, which also provided signal conditioning, recording and tabular printout of strain, deflection and load data. Photos of the test system are shown in Figures 153 to 156.

The test loading conditions and sequence are tabulated in Figures 157 to 161.

Elevator Box #1 was subjected to a bending test, with loading to 80% of D.L.L. as noted in Figure 157, followed by a torsion test to 100% D.L.L. as outlined on Figure 157. During the torsion test, stiffeners on the inner side of the lower cover at Sta. 197 and 205, were disbonded. Due to the stiffener bond failure, the test director elected to bond stiffeners on the outside of the lower cover and proceed with the fatigue test as originally intended. The






Figure 149. Strain Gage Locations



FRONT VIEW






Figure 150. Strain Gage Locations





Figure 151. Loading Points and Deflection Indicator Locations



THE PROPERTY OF THE PROPERTY O

223




Figure 153. GR/TP YC14 Elevator Box Test.-Test Article and Fixtures





Figure 154. GR/TP YC14 Elevator Bcx Test —Test Article and Fixtures



Tigure 155 off 1P Prator Box Test Article and Fixtures

HEREN CONTROL OF THE PRINT OF THE REAL PROPERTY OF




Figure 156 GR TP YC 14 Elevator Box Test Instrumentation and Control

THE PROPERTY OF THE PROPERTY O

TEST	% D.L.L.		APPLIED LO	AD - POUNDS	
	70 D.E.E.	L.P.1	L.P.2	L.P.3	L.P.4
Box No. 1 Test 1.1 Static Bending	0 20 40 60 80 60 40 20	0 -170 -340 -511 -681 -511 -340 -170	0 -63 -126 -189 -252 -189 -126 -63 0	0 1250 +501 +752 +1003 +752 +501 +250	0 +93 +186 +278 +371 +278 +136 +136
Box No. 1 Test 1.2A Static Torsion	0 20 40 60 80 0	+860 +1600 +2400 +3200 0	0 -800 -1600 -2400 -3200 0	0 -250 -500 -750 -1000	0 +250 +500 +750 +1000
Box No. 1 Test 1.2B Static Torsion	0 20 40 60 80 100 80 50 40 20 0	0 +800 +1600 +2400 +3200 +4000 +3200 +2400 +1600 +800 0	0 -800 -1600 -2400 -3200 -4000 -3200 -2400 -1600 -800 0	0 -250 -500 -750 -1000 -1250 -1000 -750 -500 -259 0	0 +250 +500 +750 +1000 +1250 +1000 +750 +500 +250 0

and some of the contraction of the color of

Aborted test after 80% load due to insufficient actuator stroke @ L.P. No. 4. Repositioned actuator and repeated as test 12.B.

Applied $\stackrel{<}{\circ}$ loads simultaneously in 20% increments in 10 seconds. Held load at each increment for data recording. Tension = +, compr = -.

Figure 157. Test - Loading Schedule, Graphite Thermoplastic YC-14 Elevator Box Test

TEST	%		APPLIED LO	AD - POUNDS	
lesi	% D.L.L.	L.P.1 L.P.2 L.P.3	L.P.4		
Box No. 1 2 > Test 1.3 Pre-Faxigue Static Torsion	0 17 34 51 67 0	0 + 662 +1324 +1986 +2649	0 - 362 -1324 -1986 -2649 0	0 -206 -412 -618 -824 0	0 +206 +412 +618 +824
Box No. 1 1st Lifetime Fatigue "A" Amplitude, MIN cycle 1 thru 75 MAX "B" Amplitude, MIN cycle 76 thru 200 MAX Repeat "A" & "B" 150 X =1 L.T. = 30,000 cycles	3 67 2 46	+ 132 +2649 + 94 +1876	- 132 -2649 - 94 -1876	- 41 -824 - 29 -577	+ 41 +824 + 29 +577
Box No. 1 Test 1.4 Post Fatigue Life 1 Static Torsion	0 17 34 51 67	0 + 662 +1324 +1986 +2649 0	0 - 662 -1324 -1986 -2649 0	0 -206 -412 -618 -824	0 +206 +412 +618 +824
Box No. 1 2nd Lifetime Fatigue	F	REPEAT AS PE	l R 1st LIFETIN	1E	
Box No. 1 Test 1.5 Post Fatigue Life 2 Static Torsion Box No. 1 3rd Lifetime Fatigue Box No. 1 Test 1.6 Post Fatigue Life 3 Static Torsion	F	REPEAT AS PE	R 1st LIFETIM	IE.	

Lower cover stiffeners @ STA 197 and 205 disbonded during test 1.2B. Exterior tee stiffeners bonded on prior to fatigue test start.

Figure 158. Test - Loading Schedule Graphite Thermoplastic YC-14 Elevator Box Test

TEST	% D.L.L.		APPLIED LO	AD - POUNDS	
1231	A D.L.L.	L.P.1	L.P.2	L.P.3	L.P.4
Box No. 1 4th Lifetime Fatigue		R	EPEAT AS PE	R 1st LIFETIM	IE
Box No. 1 Test 1.7 Post Fatigue Life 4			REPEAT AS	PER TEST 1.4	
Box No. 1 Test 1.8 Static Combined Bending and Torsion	0 20 40 60 80 100 110 120 130	0 +663 +1326 +1989 +2652 +3315 +3646 +3978 +4310 0	0 -850 -1700 -2551 -3402 -4252 -4677 -5102 -5527 0	0 -49 -99 -148 -198 -247 -272 -296 -321 0	0 +324 +648 +973 +1297 +1621 +1783 +1945 +2107
Box No. 1 Test 1.9 Static Combined Bending and Torsion Failure	0 20 40 60 80 100 110 120 130 140 150 Continuous to Failure	0 +663 +1326 +1989 +2652 +3315 +3646 +3978 +4310 +4641 +4972	0 -850 -1700 -2551 -3402 -4252 -4677 -5102 -5527 -5953 -6378	0 -49 -99 -148 -198 -247 -272 -296 -321 -346 -371	0 +324 +648 +973 +1297 +1621 ÷1783 +1945 +2107 +2269 +2432

THE SAME OF THE PROPERTY OF THE PARTY OF THE PROPERTY OF THE P

Figure 159. Test -Loading Schedule Graphite Thermoplastic YC-14 Elevator Box Test

Tee stiffeners at STA 197 and 205 were poorly bonded and were replaced with aluminum angles attached with blind rivets prior to static test 1.8.

Aborted test after 130% load due to insufficient actuator stroke at L.P. No. 3. Repositioned actuator and repeated test as 1.9.

TEST	%		APPLIED LO	AD - POUNDS	
1201	D.L.L.	L.P.1	L.P.2	L.P.3	L.P.4
Box No. 2 Test 2.1 Static Bending	0 20 40 60 80 60 40 20	0 -170 -340 -511 -681 -511 -340 -170 0	0 -63 -126 -189 -252 -189 -126 -63 - 0	0 +250 +501 +752 +1003 +752 +501 +250 0	0 +93 +186 +278 +371 +278 +186 +93 0
Box No. 2 Test 2.2A Static Torsion	0 20 40 60 80 100	0 +800 +1600 +2400 +3200 +4000	0 -800 -1600 -2400 -3200 -4000	0 -250 -500 -750 -1000 -1250	0 +250 +500 +750 +1000 +1250
Box No. 2 Test 2.3 Static Combined Bending and Torsion to failure	20 40 60 80 100	0 +663 +1326 +1989 +2652 +3315 +3646	0 -850 -1700 -2551 -3402 -4252 -4677	0 -49 -99 -148 -198 -247 -272	0 +324 +648 +973 +1297 +1621 +1783

At approximately 95% of D.L.L., the lower skin/lower front spare chord bond failed from STA 279 to 313-

Figure 160. Test - Loading Schedule Graphite Thermoplastic YC-14: Elevator Box Test

Prior to test 2.3, the failure per was repaired by bonding and installation of blind fasteners

At approximately 106% of D.L.I.., the front spar web/chord tee bond failed from outbd splice to the outbd end.

TEST		% D.L.L.		APPLIED LOA	AD - POUNDS	
, 20,		70 0.2.2.	L.P.1	L.P.3	L.P.4	
Box No. 2 Test 2.4 Static Combined Bending and Torsion to failure	≅ ▶	0 20 40 60 80 100 110 120	0 +663 +1326 +1989 +2652 +3315 +3646 +3978 +4310	0 -850 -1700 -2551 -3402 -4252 -4677 -5102 -5527	0 -49 -99 -148 -198 -247 -272 -296 -321	0 +324 +648 +973 +1297 +1621 +1783 +1945 +2107
Box No. 3 Test 3.1 Static Torsion Test		0 20 40 60 80 100 80 60 40 20 0	0 +469 +938 +1407 +1871 +2345 +1871 +1407 +938 +469 0	0 -469 -938 -1407 -1871 -2345 -1871 -1407 -938 -469 0	N.A.	N.A.

⁸ Prior to test 2.4, the failure per 7 was repaired by bonding and installation of blind fasteners.

Figure 161. Test - Loading Schedule Graphite Thermoplastic YC-14 Elevator Box Test

Failure occurred while increasing the load from 120% D.L.L. to 130%. See data for actual loads.

fatigue test with maximum loads up to 67% of D.L.L. was conducted for the equivalent of 4 life times. After each life time of fatigue testing, strain and deflection data was recorded at static load increments of 25% of the maximum fatigue load. During the fatigue test, the stiffeners bonded to the lower cover, came loose due to poor bonds. They were replaced with aluminum angles attached with blind fasteners prior to subjecting the box to a combined bending and torsion test to failure. Loading increments for the combined test are noted on Figure 159. Box #1 was loaded to approximately 130% of D.L.L. when the actuator at L.P. 3 reached the limit of its stroke. The box was unloaded and the actuator repositioned to allow more stroke in the loading direction. The test was then repeated and the loading was incremented to approximately 185% of the D.L.L. when the box failed. Post test inspection revealed that the upper cover failed at Sta. 305 to Sta. 315 and the forward spar web/chord tee bond failed from the outboard end (approx. Sta. 330) to the outboard splice (approx. Sta. 265). Upon disassembly, it was noted that the lower skin stiffener at Sta. 318 was also disbonded. Photos of Box #1 failures are in Figures 162, 163, and 164.

Elevator Box #2 was subjected to a bending test with loading as noted in Figure 160, followed by a torsion test outlined on the same page. At approximately 95% D.L.L. of the torsion loading, the lower skin/lower front spar chord bond failed from Sta. 279 to 313. The failure was repaired by bonding and installation of blind rivets. Following the repair, Box #2 was subjected to a combined bending and torsion test loading as noted in Figure 160. At approximately 106% of D.L.L., the front spar web/chord tee bond failed from the outboard splice at Sta. 265, to the outboard end of the box. Photos of Box #2 failures are in Figures 165 and 166.

THE STATE OF THE PROPERTY OF T

The front spar web/chord failure of Box #2 was repaired by bonding and blind rivets, as shown in the photograph on Figure 167. Following the repair, Box #2 was subjected to another static combined bending and torsion test to failure. As noted in Figure 161, failure occurred as the loading was being increased from 120% to 130% of D.L.L. Box #2 failed along the lower skin/rear spar chord bond, approximately from Sta. 305 to Sta. 256, and across the lower cover along the outboard row of fasteners at the outboard cover splice. Photos of the failed area of Box #2 are in Figures 168 and 169.




Figure 162. Upper Cover Failure—Test 1.9—Elev. Box No. 1




Figure 163. Front Spar Failure- Test 1.9-Elev. Box No. 1




Figure 164 Front Spar Failure - 1.9 - Elev. Box No. 1





Figure 165. Front Spar Failure -- Test 2.3 - Elev. Box No. 2



Figure 166. Front Spar Failure - Test 2.3 - Elev. Box No. 2






Figure 168. Lower Cover/Rear Spar Bond Failure - Test 2.4 - Elev. Box No. 2




Figure 169. Lower Cover Failure - Test 2.4 - Elev. Box No. 2

Box #3 was fabricated of graphite with PKXA resin system, to the configuration of the center portion of the first two elevator boxes. The aluminum end transition sections were removed from Boxes #1 and #2 and cut down to fit Box #3. Loading and reaction point fittings were likewise installed on Box #3. The test fixtures were relocated to accommodate the shorter length of Box #3, and only two actuators at L.P. #1 and L.P. #2 were used to apply a torsional load. Four deflection indicators located as per the sketch in Figure 170 were utilized to measure torsional stiffness. Photos of Box #3 in the test fixtures are in Figures 171 and 172.

The torsional loading schedule for Box #3 is in Figure 161. The static torsional stiffness was the only test on Box #3, and no attempt was made to fail the box.

THE PARTICULAR PROPERTY OF THE PROPERTY OF THE PARTY OF T




Figure 170. Load Point and EDI Locations GR/PKXA YC14 Elevator Box No. 3




Figure 171. GR/PKXA YC-14 Elevator Box No. 3 – Test Article in Fixtures




Figure 172. GR/PKXA YC-14 Elevator Box No. 3 – Test Article in Fixtures

10.0 COST AND PAYOFF ANALYSIS

Presented in this task are the cost factors associated with the various manufacturing methods and also the costs associated with the production fabrication of the YC-14 outboard elevator. Cost factors are presented in man-hours since the associated dollar factors vary between companies. Also the production times associated with thermoplastics will also fluctuate slightly depending upon facilities available since heat-up and cool-down are important considerations. Unlike thermoset materials, a slow precise heat-up rate is not required. The part must reach a temperature exceeding its softening point and the rate at which that point is reached is not particularly critical.

Table 33 shows the areas of general cost savings with reinforced thermoplastic composites. These savings apply to most methods of forming or assembly. Less labor and possibly energy savings results from not requiring a programmed cure cycle. Because thermoplastics have an infinite shelf life and no critical storage temperature requirements, savings result from less material scrappage of overaged material and eliminate the cost associated with controlled environmental storage (i.e., freezers). Since the material can be stored indefinitely, material scrap can be retained for future use or ground for molding compounds.

Thermoplastic consolidated sheet stock is rigid and tack-free enabling one man to easily handle a 4' x 8' sheet of material. This simplifies lay-up since one man can perform the lay-up of a large part that would require the efforts of 2-3 persons using a tacky thermoset prepreg system. On this program, this phenomenon proved to be a big cost saver. The individual GRTP plies are hold together at the corners with a solvent solution of dissolved resin until fusing and forming.

Another big cost saver is the ability to reprocess defective parts. Standard graphite/epoxy parts have a rejection rate of about 5%. Typical rejections are delamination, resin poor areas or poorly compacted areas. An analysis of these defects revealed that the rejection rate could be reduced to 1%

Table 33. Areas of Cost Savings

	Result
No fixed time, temperature, pressure profile	Less labor
No critical storage requirements	Fewer facility requirements
No critical shelf life	Less scrappage
Less material cutting waste	Lower material requirements
Ease of handling rigid sheet material	Less labor
Reprocessing feasible	Less part scrappage
No material bleed	Less material required
Greater damage tolerance in fabrication	Lower labor costs

through the use of GRTP parts due to their ability to be recycled or reprocessed. This feature was used several times in the course of this program to correct defective parts. Depending on the part in question and the stage of processing at which this defect occurs, this reprocessing feature can be a big cost saver.

Another area of small savings is in the elimination of bleed ply materials. Savings occur in both material and labor through the elimination of this material. The processing of GRTP requires no resin bleed under normal conditions. One layer of vacuum bleeder material is still required however, in some processing techniques to obtain uniform pressure during forming.

Laminate Consolidation - Table 18 shows the processing times associated with press, autoclave, and pultrusion. Roll-forming as a method of consolidation was never satisfactorily demonstrated under this program and therefore no production times were generated. It is estimated, based on trial runs, that if equipment could be developed the times would be similar to those experienced for pultrusion. Processing considerations are discussed in section 4.1.

Post-Forming Methods - Table 34 shows the labor hours associated with post-forming GRTP structural elements. Times shown do not i lude labor associated with tool preparation, bagging or debagging. These operations vary significantly with part complexity and size.

Element Fabrication - Table 35 shows costs comparisons made between GRTP and GREP structural element fabrications. These costs studies were conducted on a production basis assuming the most cost effective method available for both epoxy and thermoplastic parts. All elements were under 4' x 8' in area and approximately 8' in length. As is evident the cost savings for small standard elements are significant. As the size approaches 32 ft 2 , however, GRTP fabrication costs begin to significantly increase owing to the drastic increase in costs for facilities and tooling. This increase is evident in the cost change in complex shapes when the size changes for 4 ft 2 (70% savings) to 32 ft 2 (18% savings).

Table 34. Processing Times for Post-Forming

	Total Processing Time (hours)
Press forming	2.00
Autoclave Forming	4.00
● Pultrusion	2-6 inch/min
● Vacuum-forming	.1620

Table 35. Element Cost Savings with Gr/T.P.

MINISTER STATES OF A STATES OF

		Savings*
	T-Stiffeners	60%
	Hat-Stiffeners	65%
	L-Channel	72%
Elements	Honeycomb Panels	30%
	Flat Panels	42%
	(Small)	70%
	Complex Shapes	
	(Large)	18%
Onestion	Bonding	0
Operations	Drilling	59%

^{*}Over Gr/E (Labor)

Adhesive bonding operations show no cost savings since in using the standard epoxy system, the savings operations and procedures must be followed with GRTP as with epoxy composites. Savings do result in drilling since GRTP in more tolerant to hole misalignment and does not splinter or fray like an epoxy laminate.

YC-14 GRTP Elevator

是是这种,我们是是一种,我们是是是一种,我们们是是一种,我们们是一种,我们们是一种,我们们们是不是一种,我们们的,我们们是一种,我们们们们的,我们们们们们们们的

The cost predictions made early in the program for the YC-14 elevator proved to be highly accurate during final hardware fabrication. The toolin costs however, increased over the early predictions and the revised costs are shown in Table 36. In fact the resulting tooling costs for the GRTP was 1.7 times that of the epoxy tooling; however, the GRTP elevator was still more cost effective by the 10 unit.

Summary - GRTP do show cost savings over graphite/epoxy composites for routine structural elements. The degree of cost savings is highly dependent upon the fabrication methods incorporated, available facilities, component design and production quantity. A general trend that was evident is that GRTP are not cost effective over graphite/epoxy parts at production levels under 5 units. Above 10 units, GRTP, in all trades conducted in this program, proved to be the more cost effective method of fabrication.

aring and the control of the particular of the particular of the control of the c

Table 36. YC-14 Advanced Composite Horizontal Stabilizer Cost Estimate

ADVANCED COMPOSITE MATERIAL	NO. OF UNITS	PRODUC- TION HOURS	MATERIAL DOLLARS	TOOLING HOURS	TOTAL COST DOLLARS
GRAPHITE/EPOXY	1	8,563	46,926	7,742	536,076
	10	60,936	469,260	7,742	2,529,550
	100	374,666	4,692,60C	7,742	16,164,825
GRAPHITE/POLYSULFONE	1	6,050	40,015	13,147	615,925
	10	43,052	400,150	13,147	2,086,120
	100	264,712	4,001,500	13,147	12,337,270
	<u> </u>				

11.0 PKXA Evaluation, Task XII

Under Navy Contract N00019-76-C-0170 and IRAD, Boeing has evaluated a new polysulfone resin system from Union Carbide Corporation, designated PKXA. This resin, when used with graphite fiber reinforcement, exhibits similar properties to P-1700 polysulfone composites. However, PKXA contains reactive end-groups on the polymer and during the processing cycle the resin cross-links into a polymer which exhibits improved solvent resistance over P-1700. The chemical structure is shown in Figure 173.

The purpose of Task XIII was to compare the structural integrity of PKXA graphite reinforced thermoplastic (GRTP) to P-1700 GRTP and consisted of the following efforts:

- (a) A design review to ensure compatibility of PKXA with the existing P-1700 design,
- (b) Element tests,
- (c) Fabrication and test of a seven foot section of the YC-14 elevator.

These activities are discussed in this section.

PKXA Element Tests

Static tests were conducted on rail shear, fusion bonded lap joints, mechanically attached lap joints and fracture panel specimens. Fatigue tests were also conducted on rail shear specimens to determine properties of Graphite/PKXA structural elements.

$$(CH_{3}O)_{3} Si - \left(-O - \bigcirc -\overset{CH_{3}}{\overset{1}{\leftarrow}} - O - \bigcirc -\overset{O}{\overset{\parallel}{\rightarrow}} - \bigcirc -\overset{O}{\overset{\parallel}{\rightarrow}} - \bigcirc -\overset{O}{\overset{\parallel}{\rightarrow}} - O - \bigcirc -\overset{O}{\overset{\parallel}{\rightarrow}} - \bigcirc -\overset{O}{\overset{\parallel}{\rightarrow}} - O - \bigcirc -\overset{O}{\overset{\parallel}{\rightarrow}} - \bigcirc -\overset{O}{\overset{\bullet}{\rightarrow}} -\overset{O}{\overset{\bullet$$

Figure 173. Chemical Formulas of PKXA and P-1700 Polysulfone

Thickness, inches	Cross section area, sq. in.	Ultimate shear stress, psi at 70°F	Shear modulus, G, 10 ⁶ psi
0.0620	0.3131	22,600	3.6
0.0623	0.3146	22.000	3.4
0.0571	0.2883	23,600	3.9

Table 36. PKXA Static Rail Shear Test Results

Static rail shear specimens were tested at room temperature in a 120,000 pound capacity Baldwin universal test machine. Specimens were instrumented with a single element strain gage criented at 45° to the specimen center line, to measure shear strain. Strain and load, as measured by the test machine, were recorded on a Honeywell Model 530, X-Y plotter. The results are shown in Table 36.

A commendation of the second s

Fusion bonded and mechanically fastened lap joint specimens were tested in a 120,000 pound capacity Baldwin universal test machine. Load vs. test machine crosshead displacement was recorded on the Baldwin X-Y plotter. Tests were conducted at room temperature and 160°F as noted on the data sheets. Elevated temperature tests were conducted in a resistance heated box furnace with a Thermac power controller. Specimen temperatures were sensed by Chromel-Alumel thermocouples bonded to the specimen, and indicated by a Doric digital temperature indicator. Results of the mechanically attached and fusion bonded lap shear specimens are shown in Tables 37 and 38, respectively.

Fracture panel specimens were tested in a 120,000 pound capacity Baldwin universal test machine at room temperature. Load vs. test machine crosshead displacement was recorded on the Bladwin X-Y plotter. The results are shown in Table 39.

Rail shear fatigue tests were conducted in a Sonntag SF-10U universal fatigue machine at a minimum/maximum load ratio R = .05. Specimens were loaded at a frequency of 30 Hz, at temperatures of 70 and 160°F. Specimes s were heated by Chromalox strip heaters attached to the test fixture and surrounded by fiberglass insulation. Heater power was controlled by a Thermac power controller. Specimen temperature was sensed by Chromel-Alumel thermocouples bonded to the specimen gage section and indicated on a Doric digital temperature indicator. The number of loading cycles to failure for each specimen was recorded. These data are presented in Table 40. A comparison of these data with P-1700 data is shown in Figure 174. A general comparison of static PKXA data with static P-1700 data is shown in Table 41.

The fusion bond and mechanical attachment tests showed that the PKXA graphite composite load transfer capabilities were equivalent to the P-1700 graphite composite materials. This indicated that the load transfer details and fabrication procedures used for the P-1700 did not

Specimen axis to layup	Ultimate load, pounds	Type of failure		
0-900	730	1		
0-90°	688			
± 45°	1,034			
<u>+</u> 45°	782			
E/D = 2, fastener = BAC B30NF-4, width = 1.00 4 plies, fabric				

jedzinicaj krazi kojezu prakod karzokanana mirka praka prakadnica koraziona karanara karanara karanara

Table 37. PKXA Mechanical Attachment, Lap Shear Test Results

Lap length, inches	Lap width, inches	Test temperature, ^o F	Ultimate load, pounds
0.52	1.013	70	1,849
0.52	1.013	70	1,836
0.52	1.013	70	2,068
0.52	1.017	70	2,256
0.52	1.018	180	1,775
0.52	1.018	160	2,400
0.52	1.016	180	1,328
0.52	1.016	160	2,125

⁴ plies, fabric, 0, 90°

Table 38. PKXA Fusion Bond, Lap Shear Test Results 256

Specimen axis to layup	Thickness, inches	Width, inches	Ultimate load, pounds	Gross area stress, psi		
± 45°	0.058	5.955	4,200	12,100		
0-90°	0.055	5.995	6,460	19,500		
P $\frac{1.00}{1.00}$ P 0.50 dia						

Table 39. PKXA Fracture Panel, Tension Test Results

Thickness, inches	Cross section area, inches	Test temperature, oF	Maximum fatigue stress, psi	Cycles to failure
0.061	0.3080	70	17,500	, 438,000
0.059	0.2980	70	15,000	2,566,000
0.059	0.2980	70	20,000	33,000
0.057	0.2880	160	15,000	868,000
0.058	0.2930	160	17,500	102,000

R = Minimum/maximum stress = 0.05

Table 40. PKXA Rail Shear Fatigue Results

⁴ plies, T-300 fabric at ± 45
7-13




Figure 174. PKXA-P-1700 Rail Shear Fatigue Data Comparison

Element	PKXA	P-1700
Fracture panel (± 45)	4,200 в	5,120 lb
Fracture panel (0, 90)	6,460 lb	8,140 lb
Mechanical fastener tests Load (E/D = 2)		
Laminate (0, 90)	730 1ь	748 lt
Laminate (0, 90)	688 lb	638 lb
Laminate ± 45	1,034 lb	937 lb
Laminate ± 45	782 lb	813 ib
Fusion bond		
Laminate (0, 90) RT	4,125 psi	3,110 psi 🗀
Laminate (0, 90) RT	4,512 psi	2,990 psi
Laminate (0, 90) 160 ⁰	4,800 psi	2,500 psi
Laminate (0, 90) 160 ⁰	4,250 psi	2,540 psi
Static rail shear	22,800	30,900
	22,200	31,100
	23,800	32,500

Based on rail thear fusion bond specifications

Table 41. PKXA Polysulfone Static Element Test Data Commarison

require changes to facilitate the use of PKXA mater:al. The fracture strength and fatigue capabilities were generally lower than the P-1700 graphite material but the modulus values are comparable. All properties were more than adequate for the proposed stiffness critical design of the YC-14 elevator. Data obtained from the (±45°) graphite/PKXA center notched panel shows that its gross fracture strength is below the equivalent graphite/epoxy and graphite/P-1700 but well above the design limit strain. Likewise, the PKXA composite is lower than the equivalent P-1700 in rail shear strength but with fatigue capabilities more than adequate to meet the design requirements.

PKXA - Elevator Box Section Fabrication and Test

During this task a 7' section of the YC-14 elevator box was fabricated of graphite fabric/PKXA composite construction. The PKXA resin was received in powder (fluff) form, put into solution using methylene chloride, and impregnated onto graphite fabric (24 x 24) to a nominal resin content of 35%. The prepreg was oven dried for 1/2 hour at 250° F to remove residual solvent. Then, the prepreg was consolidated into four ply sheet stock in an autoclave at 600° F for thirty minutes using 200 psi pressure.

Once the prepreg and sheet stock had been prepared, detail part fabrication and elevator assembly tooling/procedures used were the same as for the full size P-1700 polysulfone elevator boxes. The completed PKXA box section is shown in test, Figure 171.